





report date: 2024-03-29

General information

Make	SUZUKI
Model	GRAND VITARA SZ5 DDIS
Colour	Silver
Year of manufacture	2013
Top speed	106 mph
0 - 60 mph	13.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	300 Nm at 2.000 rpm
Engine capacity	1.870 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/9



MOT history

MOT expiry date	2020-08-15
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	9
Total items failed	3

MOT #6		2019-08-02 09:25
MOT test	number	710493559867
Result		✓ Passed
Next expi	ry date	2020-08-15
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #5	2019-08-01 13:56	
MOT test number	584659445257	
Result	× Failed	
Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Fail Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))	

CarCheck.co.uk page 2/9



MOT #4 2018-08-10 11:04

MOT test number 744182119881

Result ✓ Passed

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3 2017-08-16 15:27

MOT test number 385106311316

MOT #2 2017-01-12 15:30

MOT test number 308285398248

Result
✓ Passed

Advice Rear Brake discs slightly pitted

Advice Front Tyre edges worn

Advice Front Brake discs scored -Inner faces

MOT #1 2016-01-06 10:19

MOT test number 646392703857

Result
✓ Passed

CarCheck.co.uk page 3/9



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 4/9



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 5/9



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		KI

	More info	
	More into	>
Plate changes		
See in this check if this SUZUKI had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 6/9



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this SUZUKI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 7/9



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2013-01-08
Last registration	2019-08-02
Complete history	See info



Registration #1	2013-01-08	10 mi
Registration #2	2016-01-06	22.625 mi
Registration #3	2017-01-12	29.369 mi
Registration #4	2017-08-16	31.847 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.177 es

More info >

CarCheck.co.uk page 8/9



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1695 mm
Length	4500 mm
Wheel base	2800 mm
Kerb weight	1735 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	F9QC-025222

CarCheck.co.uk page 9/9