



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I10 GO
Colour	White
Year of manufacture	2016
Top speed	96 mph
0 - 60 mph	14.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	65 BHP
Max. torque	95 Nm at 3.500 rpm
Engine capacity	998 cc
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	60.1 mpg
CO2 emission	108 g/km
CO2 label	B







Internet history

Entry 2

Date	2021-02-23
Pictures	21
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-01-22
Pictures	1
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-11-29
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	3

MOT #6	2023-11-13 14:10
MOT test number	465840402430
Result	✓ Passed
Next expiry date	2024-11-29

MOT #5	2022-11-04 09:36
MOT test number	271249208955
Result	✓ Passed

MOT #4	2021-11-09 10:39
MOT test number	645165689532
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3	2020-11-23 13:32
MOT test number	748968480266
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing on inner edge & 3mm (5.2.3 (e))



MOT #2	2019-11-30 13:21
MOT test number	444582730311
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge tyre close to wear indicators (5.2.3 (e))

MOT #1	2019-11-25 15:00
MOT test number	897031801739
Result	✗ Failed
Advice	Brake pad(s) wearing thin Offside and nearside rear inner pads wearing low (1.1.13 (a) (ii))
Advice	Oil leak from engine sump seal
Advice	Items removed from driver's view prior to test from mirror
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Brake disc in such a condition that it is seriously weakened inner face badly deteriorated (1.1.14 (a) (ii))
Advice	Parking brake effort low on both sides 80 - 70, possible due to condition of brake discs
Advice	Offside Front Tyre worn close to legal limit/worn on edge tyre close to wear indicators (5.2.3 (e))
Fail	Offside Rear Brake disc in such a condition that it is seriously weakened inner face badly deteriorated (1.1.14 (a) (ii))
Advice	Service brake fluctuating, but not excessively Offside and nearside rears (1.2.1 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
29 November 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	29 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-11-29
Last registration	2023-11-13
Complete history	See info



Registration #1	2016-11-29	17 mi
Registration #2	2019-11-25	12.490 mi
Registration #3	2019-11-30	12.566 mi
Registration #4	2020-11-23	15.708 mi
Registration #5	2020-11-23	15.708 mi
Registration #6	2020-11-23	15.708 mi
Registration #7	2020-11-23	15.708 mi
Registration #8	2020-11-23	15.708 mi
Registration #9	2020-11-23	15.708 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	80%
Pedestrian	71%
Safety systems	56%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1660 mm
Height	1500 mm
Length	3665 mm
Wheel base	2385 mm
Kerb weight	933 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G3LAFM003200