



report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT COURIER KOMBI TDCI
Colour	White
Year of manufacture	2017
Top speed	106 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 kW / 95 HP / 74 BHP
Max. torque	215 Nm at 4.200 rpm
Engine capacity	1.499 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	78.5 mpg
Consumption combined	72.4 mpg
CO2 emission	99 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-06-07
Pictures	27
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-07-04
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	6
Total items failed	17

MOT #8	2023-07-05 11:26
MOT test number	916537411423
Result	✓ Passed
Next expiry date	2024-07-04

MOT #7	2023-07-04 10:17
MOT test number	617498147759
Result	✗ Failed
Fail	Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))
Fail	Offside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))
Advice	Offside Rear lens broken
Fail	Offside Rear Rear fog lamp does not emit a steady red light (4.5.4 (a))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))
Fail	Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6	2022-07-01 15:00
MOT test number	419451446871
Result	✓ Passed

**MOT #5** 2022-06-30 12:26**MOT test number** 829735176235**Result** ✗ Failed**Fail** Offside Front Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Exhaust emissions exceed default limit of 0.7m-1 (8.2.2.2 (b))**Advice** Offside Front tyre worn on inner edge**Advice** Offside Rear Nail in tyre**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #4** 2021-07-02 13:57**MOT test number** 339540741439**Result** ✓ Passed**MOT #3** 2021-06-28 15:51**MOT test number** 177219973523**Result** ✗ Failed**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Nail in tyre



MOT #2	2020-09-22 07:47
MOT test number	766301849556
Result	✓ Passed
Advice	Offside Rear Nail in tyre towards outer tyre wall

MOT #1	2020-09-21 15:22
MOT test number	191521620892
Result	✗ Failed
Fail	Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
Fail	Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
Advice	Offside Rear Nail in tyre towards outer tyre wall



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
4 July 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	4 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YN67OBR
Plate since	2019-09-29
Current registration	YN67OBR
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-20
Last registration	2023-07-05
Complete history	See info



Registration #1	2017-09-20	10 mi
Registration #2	2020-09-21	28.512 mi
Registration #3	2020-09-22	28.512 mi
Registration #4	2020-09-22	28.512 mi
Registration #5	2021-06-28	29.051 mi
Registration #6	2021-06-28	29.051 mi
Registration #7	2021-06-28	29.051 mi
Registration #8	2021-06-28	29.051 mi
Registration #9	2021-06-28	29.051 mi
Registration #10	2021-06-28	29.051 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	84%
Pedestrian	74%
Safety systems	56%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2060 mm
Height	1747 mm
Length	4157 mm
Wheel base	2 mm
Kerb weight	1203 kg
Max. allowed weight	1780 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2

Engine number	HA33114
---------------	---------