





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Black
Year of manufacture	2005
Top speed	102 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	81 BHP
Max. torque	116 Nm at 3.200 rpm
Engine capacity	1.341 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/13



# Internet history


#### Entry 1

Date 2021-09-18

Pictures 5

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-01
MOT pass rate	84 %
MOT passed	16
Failed MOT tests	3
Total advice items	13
Total items failed	3

MOT #19	2023-10-03 10:55
MOT test number	294968163954
Result	✓ Passed
Next expiry date	2024-11-01
Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b)	) (i))

MOT #18		2022-10-20 07:23
MOT test	number	810158380626
Result		✓ Passed
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated	d (6.1.7 (g) (i))
Minor	Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4	l (b) (i))
Minor	Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources	(4.7.1 (b) (i))

MOT #17	2021-10-11 06:14
	2021-10-11 00.14
MOT test number	636076106917
Result	✓ Passed
MOT #16	2020-11-02 11:17
MOT test number	838252653309
Result	✓ Passed

CarCheck.co.uk page 3/13



MOT #15 2020-10-30 11:12

**MOT test number** 634785513286

**Result** X Failed

Fail Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #14 2019-09-26 15:40

**MOT test number** 990626701998

**Result** 
✓ Passed

MOT #13 2018-09-21 15:59

MOT test number 117803071251

Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #12 2017-09-29 16:32

MOT test number 935110645602

Result \( \sqrt{Passed} \)

**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #11 2016-09-29 16:23

**MOT test number** 168610616485

**MOT #10** 2016-09-29 16:23

**MOT test number** 957843638737

**Result** X Failed

**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

CarCheck.co.uk page 4/13



KU55KYA

report date: 2024-03-28

MOT #9 2015-09-21 16:36

**MOT test number** 374690067004

**Result** ✓ Passed

MOT #8 2014-10-02 11:39

**MOT test number** 227285674272

Result 

Passed

MOT #7 2013-09-11 12:47

**MOT test number** 926314753291

Result \( \sqrt{Passed} \)

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #6 2013-09-11 12:47

MOT test number 356524453265

Result X Failed

**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #5 2012-10-01 16:24

**MOT test number** 318535972447

MOT #4 2011-08-31 16:57

**MOT test number** 996513541225

**Result** ✓ Passed

**Notice** Nail in offside rear tyre

CarCheck.co.uk page 5/13



MOT #3 2010-08-17 14:35 **MOT test number** 882879520287 ✓ Passed Result MOT #2 2009-08-28 13:24 352440349288 **MOT test number** Result ✓ Passed MOT #1 2008-08-29 14:49 132942048209 **MOT test number** Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



#### Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	1 November 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	,
Current registration	IK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

**Contact info** 

More info >

CarCheck.co.uk page 11/13



## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-09-01
Last registration	2023-10-03
Complete history	See info



Registration #1	2005-09-01	9 mi
Registration #2	2008-08-29	10.606 mi
Registration #3	2009-08-28	13.993 mi
Registration #4	2010-08-17	16.958 mi
Registration #5	2011-08-31	23.252 mi
Registration #6	2012-10-01	29.249 mi
Registration #7	2013-09-11	34.540 mi
Registration #8	2014-10-02	39.690 mi
Registration #9	2015-09-21	44.104 mi
Registration #10	2016-09-29	49.110 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		71.777 es

More info >

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	1095 kg
Max. allowed weight	1500 kg

# Additional information

·	
Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/

Number of axles 2

**Engine number** G4EA4688403