



report date: 2024-03-28

General information

Make	MAZDA
Model	6 D BUSINESS LINE
Colour	Blue
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	129 BHP
Max. torque	340 Nm at 1.800 rpm
Engine capacity	2.183 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	138 g/km
CO2 label	E





MOT history

MOT expiry date	2025-02-22
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	38
Total items failed	5

MOT #14 2024-02-14 13:20

MOT test number 706083204460

Result ✓ Passed

Next expiry date 2025-02-22

Advice Nearside Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

Advice Front Tyre worn close to legal limit/worn on edge both front tyres (5.2.3 (e))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

Advice Offside Rear Suspension arm corroded but not seriously weakened all (5.3.3 (b) (i))

Advice Front Steering component deformed but serviceable (2.1.3 (c) (i))

MOT #13 2023-02-22 14:00

MOT test number 233635481449

Result ✓ Passed

**MOT #12** 2023-02-20 15:00**MOT test number** 243165114670**Result** ✗ Failed**MAJOR** Front Suspension arm ball joint excessively worn both (5.3.4 (a) (i))**MAJOR** Brake lever has insufficient reserve travel (1.1.2 (a))**MOT #11** 2022-02-18 16:50**MOT test number** 366656138378**Result** ✓ Passed**Minor** Suspension arm ball joint dust cover severely deteriorated both front lower (5.3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm ball joint has slight play slight lift (5.3.4 (a) (i))**Advice** Tyre worn close to legal limit/worn on edge both front below 1.6mm (5.2.3 (e))**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))**MOT #10** 2022-02-18 16:50**MOT test number** 932549242125**Result** ✗ Failed**Advice** Tyre worn close to legal limit/worn on edge both front below 1.6mm (5.2.3 (e))**Advice** Nearside Front Lower Suspension arm ball joint has slight play slight lift (5.3.4 (a) (i))**Minor** Suspension arm ball joint dust cover severely deteriorated both front lower (5.3.4 (b) (i))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Brake pipe corroded, covered in grease or other material both front (1.1.11 (c))

**MOT #9** 2021-02-23 12:33**MOT test number** 922560590288**Result** ✓ Passed

- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #8 2019-07-18 15:05**MOT test number** 289484062256**Result** ✓ Passed

- Advice** Nearside Rear Nail in tyre

MOT #7 2019-07-18 12:14**MOT test number** 210183591707**Result** ✗ Failed

- Advice** Nearside Rear Nail in tyre
- MAJOR** Windscreen washer provides insufficient washer liquid both front (3.5 (a))

MOT #6 2018-07-21 10:16**MOT test number** 281530987496**Result** ✓ Passed**MOT #5** 2017-07-24 09:40**MOT test number** 479261766817**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2017-07-18 08:16

MOT test number

385457700236

Result**✗ Failed**

- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

2016-09-20 10:36

MOT test number

165600703590

Result**✓ Passed**

- Advice** Both front brake discs corroded/worn
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Rear panel damaged

MOT #2

2015-09-29 10:38

MOT test number

182900018438

Result**✓ Passed**



MOT #12014-09-16 15:02

MOT test number156779354227

Result

✓ Passed

- Notice

Both front tyres worn on edges
- Notice

N/s/r tyre slightly worn on edges
- Advice

Parking brake lever has little reserve travel (3.1.6b)
- Notice

O/s/r tyre worn on inside edge
- Notice

Both rear brake discs corroded/worn



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
22 February 2025

Tax status	Valid until 1 September
Days left	125
MOT expiry date	22 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-09-30
Last registration	2024-02-14
Complete history	See info



Registration #1	2011-09-30	13 mi
Registration #2	2014-09-16	27.508 mi
Registration #3	2015-09-29	34.744 mi
Registration #4	2016-09-20	39.229 mi
Registration #5	2017-07-18	42.677 mi
Registration #6	2017-07-24	42.677 mi
Registration #7	2018-07-21	50.401 mi
Registration #8	2019-07-18	60.014 mi
Registration #9	2020-05-20	65.377 mi
Registration #10	2021-05-20	70.777 mi
Registration #11	2022-05-20	76.177 mi
Registration #12	2023-05-20	81.577 mi
Registration #13	2024-02-14	86.977 mi
Registration #14	2024-02-14	86.977 mi
Registration #15	2024-02-14	86.977 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1550 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	R2 10291334