



RENAULT

EJI2BPE

report date: 2024-03-29

General information

Make	RENAULT
Model	TRAFIC SL27 DCI S/R P/V
Colour	White
Year of manufacture	-
Top speed	99 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	300 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	32.8 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.9 mpg





Internet history

Entry 1

Date	2021-07-09
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #11</b>	2023-06-23 08:10
<b>MOT test number</b>	634526555946
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2024-07-04
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Minor</b>	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

<b>MOT #10</b>	2022-06-27 08:06
<b>MOT test number</b>	219754927143
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Nearside Rear Nail in tyre

<b>MOT #9</b>	2021-07-05 16:14
<b>MOT test number</b>	380694809489
<b>Result</b>	✓ Passed

<b>MOT #8</b>	2019-12-20 10:38
<b>MOT test number</b>	256180628996
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2019-01-07 16:02
<b>MOT test number</b>	181058651117
<b>Result</b>	✓ Passed

**MOT #6** 2019-01-07 09:16**MOT test number** 571961274701**Result** ✗ Failed**Fail** Loading door likely to open inadvertently or not remain closed rear door (6.2.3 (b) (ii))**Fail** Nearside Rear Position lamp showing white light to the rear (4.2.3 (a) (ii))**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Central Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))**MOT #5** 2018-01-04 11:12**MOT test number** 869699042229**Result** ✓ Passed**MOT #4** 2018-01-04 09:29**MOT test number** 295288421551**Result** ✗ Failed**Fail** Offside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Fail** Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)**MOT #3** 2017-01-10 13:49**MOT test number** 946087034591**Result** ✓ Passed**MOT #2** 2016-02-01 12:08**MOT test number** 635669874615**Result** ✓ Passed



MOT #1	2015-05-01 13:02
MOT test number	358111125139
Result	✓ Passed



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	EJ12BPE
Plate since	2019-03-29
Current registration	EJ12BPE
Plate since	2019-03-29

More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT FINANCE
Date of agreement	01/01/2024
Agreement type	FINANCE
Agreement term	36 months
Agreement number	123456789
Contact info	01234 567890

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-04-30
Last registration	2023-06-23
Complete history	<a href="#">See info</a>



Registration #1	2012-04-30	23 mi
Registration #2	2015-05-01	49.861 mi
Registration #3	2016-02-01	58.110 mi
Registration #4	2017-01-10	66.725 mi
Registration #5	2018-01-04	76.386 mi
Registration #6	2018-01-04	76.387 mi
Registration #7	2019-01-07	85.024 mi
Registration #8	2020-06-23	85.024 mi
Registration #9	2021-06-23	85.024 mi
Registration #10	2022-06-23	85.024 mi
Registration #11	2023-06-23	85.024 mi
Registration #12	2024-03-29	85.024 mi
Registration #13	2024-03-29	85.024 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	C018034