



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Green
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	26.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-07-01
Pictures	4
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-10
Pictures	4
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history****MOT #18** 2022-03-24 14:13**MOT test number** 221345356089**Result** ✓ Passed**Next expiry date** 2023-03-23**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** N/s mirror mount slightly loose**Advice** O/s mirror glass cracked**Advice** Tyre slightly damaged/cracking or perishing Both rear tyres (5.2.3 (d) (ii))**Advice** Both headlights have weak patterns/slightly weak patterns**MOT #17** 2021-01-30 09:10**MOT test number** 620927865272**Result** ✓ Passed**Advice** Both front top mounts have slight play**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #16** 2019-11-27 09:55**MOT test number** 153948288736**Result** ✓ Passed**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #15** 2019-11-25 14:26**MOT test number** 390644818382**Result** ✗ Failed**Advice** Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**MAJOR** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #14** 2018-12-01 11:10**MOT test number** 250994462681**Result** ✓ Passed**Advice** Nearside Front Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))**Advice** Slightly oil leak**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #13** 2017-03-16 12:36**MOT test number** 532207867798**Result** ✓ Passed**MOT #12** 2016-03-09 14:08**MOT test number** 721491117692**Result** ✓ Passed**MOT #11** 2015-03-14 14:56**MOT test number** 186603875033**Result** ✓ Passed

**MOT #10** 2014-02-20 15:03**MOT test number** 878611354014**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #9** 2013-03-18 15:35**MOT test number** 879297473006**Result** ✓ Passed**Notice** Centre exhaust bracket has weld broken but still supported**MOT #8** 2012-03-12 14:40**MOT test number** 658112672028**Result** ✓ Passed**Notice** Nail in offside rear tyre**Notice** Centre exhaust bracket broken at weld.**MOT #7** 2011-02-16 17:51**MOT test number** 899307141026**Result** ✓ Passed**MOT #6** 2010-06-29 15:57**MOT test number** 324080180174**Result** ✓ Passed

**MOT #5** 2010-06-29 10:22**MOT test number** 734920980150**Result** ✗ Failed**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Windscreen has a sticker or other obstruction encroaching by more than 10mm within zone 'A' (8.3.1b)**MOT #4** 2009-07-02 10:51**MOT test number** 251523189143**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #3** 2008-07-05 10:18**MOT test number** 820947588137**Result** ✓ Passed**MOT #2** 2007-07-17 16:36**MOT test number** 842758397191**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2006-03-18 11:43**MOT test number** 143937376423**Result** ✓ Passed



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BF03XJN
Plate since	2019-06-29
Current registration	 BF03XJN
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-03-28
Last registration	2022-03-24
Complete history	See info



Registration #1	2003-03-28	8 mi
Registration #2	2006-03-18	28.030 mi
Registration #3	2007-07-17	36.044 mi
Registration #4	2008-07-05	42.239 mi
Registration #5	2009-07-02	45.771 mi
Registration #6	2010-06-29	49.498 mi
Registration #7	2010-06-29	49.498 mi
Registration #8	2011-02-16	54.554 mi
Registration #9	2012-03-12	61.934 mi
Registration #10	2013-03-18	69.311 mi
Registration #11	2014-02-20	78.303 mi
Registration #12	2015-03-27	85.277 mi
Registration #13	2016-03-27	92.251 mi
Registration #14	2017-03-27	99.225 mi
Registration #15	2018-03-27	106.199 mi
Registration #16	2019-03-27	113.173 mi
Registration #17	2020-03-27	120.147 mi
Registration #18	2021-03-27	127.121 mi
Registration #19	2022-03-27	134.095 mi
Registration #20	2023-03-27	141.069 mi
Registration #21	2024-03-27	148.043 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

Engine number

BFS 009754