





General information

Make	NISSAN
Model	350 Z V6
Colour	Silver
Year of manufacture	2006
Top speed	155 mph
0 - 60 mph	5.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	296 BHP
Max. torque	358 Nm at 4.800 rpm
Engine capacity	3.498 cc
Cylinders	6
Fuel type	Petrol
Consumption city	16.8 mpg
Consumption extra urban	32.1 mpg
Consumption combined	24.1 mpg
CO2 emission	280 g/km
CO2 label	М







Internet history	
Entry 1	
Date	2021-07-12
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-05
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	19
Total items failed	1

MOT #18	2	2024-03-06 15:20
MOT test	number	694669925194
Result		✓ Passed
Next expi	ry date	2025-03-05
Advice	Rear subframe slight corrosion	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #17	2022-08-03 11:23
MOT test number	663241065214
Result	✓ Passed

MOT #16	2021-08-04 12:11
MOT test number	995789328828
Result	✓ Passed

MOT #15	2021-03-23 15:09
MOT test number	975243066925
Result	✓ Passed
Advice Front to rear brake pipes have plastic cover over	





MOT #14		2021-03-23 08:32
MOT test	number	389859939656
Result		🗙 Failed
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (z))
Advice	Front Inner Brake disc worn, but not excessively x 2 (1.1.14 (a) (i))	
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
MAJOR	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice	Front to rear brake pipes have plastic cover over	

MOT #13	2020-07-22 14:05
MOT test number	488010416088
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #12	2019-07-10 09:11
MOT test number	722088127113
Result	✓ Passed

MOT #11	2019-05-16 07:28
MOT test number	715151668316
Result	✓ Passed
Advice Vehicle slight corroded under body and suspension	





MOT #10	201	8-06-12 08:39
MOT test	number 4	94567580808
Result		🗸 Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))	

MOT #9	2017-06-13 07:15
MOT test number	917507006885
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (7.1.2)	

МОТ #8	2016-06-01 07:43
MOT test number	227166450199
Result	✓ Passed
MOT #7	2015-06-05 08:52
MOT test number	777936955163
Result	✓ Passed

MOT #6	2014-05-22 11:52
MOT test number	438312044117
Result	✓ Passed

MOT #5		2013-05-15 10:25
MOT test	number	429525933114
Result		✓ Passed
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Rear Exhaust has a minor leak of exhaust gases (7.1.2)	





MOT #4		2012-05-21 12:44
MOT test number		845112642124
Result		✓ Passed
MOT #3		2012-05-21 12:44
MOT test number		948492642174
Result		🗙 Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)	
MOT #2		2011-05-20 16:33
MOT test number		967970541123
Result		✓ Passed
Advice Offside Rear Tyr	e worn close to the legal limit (4.1.E.1)	

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-06-07 12:38
MOT test number	930678950108
Result	Passed
Notice Suface rust to front and rear discs	



Tax & MOT check

✓ Taxed	✓ MOT Expires: 5 March 2025
1 March 2025 Tax status	5 March 2025 Valid until 1 March
Days left	307
MOT expiry date	5 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	К
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	 · · ·
Category	 AMPL
Туре	

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this NISSAN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



VO06EOF report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-04-27
Last registration	2024-03-06
Complete history	See info



Registration #1	2006-04-27	8 mi
Registration #2	2010-06-07	27.723 mi
Registration #3	2011-05-20	34.441 mi
Registration #4	2012-05-21	38.770 mi
Registration #5	2013-05-15	40.935 mi
Registration #6	2014-05-22	44.172 mi
Registration #7	2015-06-05	45.782 mi
Registration #8	2016-06-01	46.310 mi
Registration #9	2017-06-13	46.429 mi
Registration #10	2018-06-12	46.527 mi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		
-		11.117 es
Registration #14		11.777 es
		0.000 est 0.000 est 0.000 est
Registration #14		01,000 est 01,000 est 01,000 est 01,000 est
Registration #14 Registration #15		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est
Registration #14 Registration #15 Registration #16		01,000 est 01,000 est 01,000 est 01,000 est 01,000 est 01,000 est





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
\$0566	
\$0567	
S0569	

Dimensions & weight

Width	1815 mm
Height	1320 mm
Length	4310 mm
Wheel base	2650 mm
Kerb weight	1542 kg
Max. allowed weight	1820 kg
Additional information	
Fuel tank canacity	80.1

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Engine number	797484