





report date: 2024-03-29

## General information

Make	MAZDA
Model	2 TS2
Colour	Silver
Year of manufacture	2011
Top speed	107 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	84 BHP
Max. torque	122 Nm at 3.500 rpm
Engine capacity	1.349 сс
Cylinders	4
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	67.3 mpg
Consumption combined	54.3 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

## Entry 2

Date 2023-11-24

Pictures 33

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-05-28

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



**MOT** history

MOT expiry date	2024-06-20
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	22
Total items failed	3

MOT #11		2023-06-21 13:52
MOT test	number	236356471089
Result		✓ Passed
Next exp	iry date	2024-06-20
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5	5.2.3 (d) (ii))
Advice	Offside Rear light lens damaged	
Advice (c))	Offside Rear Brake pipe corroded, covered in grease or other material sligh	ntly corroded (1.1.11
Minor	Offside Front Lower Suspension arm ball joint dust cover severely deteriorate	ted (5.3.4 (b) (i))
Advice	Nearside rear bumper damaged	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2	2.3 (d) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Central exhaust heat shield not fully secure	

CarCheck.co.uk page 3/12



**MOT #10** 2023-06-16 10:48

MOT test number 351338712605

**Result** X Failed

Minor Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside rear bumper damaged

Advice Nearside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii))

Advice Offside Rear Brake pipe corroded, covered in grease or other material slightly corroded (1.1.11 (c))

**Advice** Central exhaust heat shield not fully secure

Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Rear light lens damaged

Advice Offside Rear Tyre slightly damaged/cracking or perishing tyre cracking (5.2.3 (d) (ii))

**Fail** Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt dust cover split (5.3.4 (b) (ii))

**MOT #9** 2022-06-11 15:57

MOT test number 332842803937

Result \( \sqrt{Passed} \)

Advice Brake pipe corroded, covered in grease or other material nsf/osf/nsr/osr (1.1.11 (c))

**Advice** Coil spring corroded nsr/osr (5.3.1 (b) (i))

**Advice** Underside body/component corrosion

MOT #8 2021-06-01 15:44

**MOT test number** 935315968685

**Result** ✓ Passed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



MOT #7 2020-05-29 10:36

**MOT test number** 284220043687

MOT #6 2019-05-24 13:30

**MOT test number** 593030735250

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5 2018-05-16 13:33

**MOT test number** 725944183272

Result \rightarrow Passed

MOT #4 2017-06-12 15:33

**MOT test number** 437502117837

MOT #3 2016-06-01 12:37

**MOT test number** 875716353304

**Result** ✓ Passed

MOT #2 2015-06-02 13:35

MOT test number 889613755187

Result 

Passed

MOT #1 2014-06-13 14:06

MOT test number 138884564131

Result 

Passed

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 December
Days left	215
MOT expiry date	20 June 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when miscory		
For how long did the current and previous owner(s) have this MAZDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full research		
***************************************		
manage and the same and the sam		
***************************************		
***************************************		
	More info >	
Plate changes		
See in this check if this MAZDA had different number plates.		
Number of plates		,
Current registration	UK SIS SIS	
Plate since		
Current registration	OK NEW TOTAL	
Plate since		
	More info >	

CarCheck.co.uk page 9/12



### Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



# Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-06-15
Last registration	2023-06-21
Complete history	See info



Registration #1	2011-06-15	12 mi
Registration #2	2014-06-13	24.276 mi
Registration #3	2015-06-02	32.201 mi
Registration #4	2016-06-01	40.106 mi
Registration #5	2017-06-12	46.312 mi
Registration #6	2018-05-16	50.687 mi
Registration #7	2019-05-24	67.099 mi
Registration #8		11.177 es
Registration #9		11.777 es
Registration #10		11.177 es
Registration #11		11.777 es
Registration #12		11.117 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1695 mm
Height	1475 mm
Length	3885 mm
Wheel base	2490 mm
Kerb weight	1025 kg
Max. allowed weight	1455 kg

## Additional information

Fuel tank capacity	42 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5
Number of axles	2
Engine number	ZJ 915524

CarCheck.co.uk page 12/12