





report date: 2024-03-29

General information

| Make | VOLKSWAGEN | |
|---------------------|-----------------------------|--|
| Model | ARTEON ELEGANCE TSI EVO DSG | |
| Colour | Grey | |
| Year of manufacture | 2019 | |
| Top speed | 137 mph | |
| 0 - 100 km/h | 8.9 seconds | |
| 0 - 60 mph | 8.6 seconds | |
| Gearbox | 7 speed Semi Auto | |

Engine & fuel consumption

| Power | 110 kW / 150 HP / 148 BHP |
|-------------------------|---------------------------|
| Max. torque | 250 Nm at 1.500 rpm |
| Engine capacity | 1.498 сс |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 0.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | Е |



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

Entry 1

Date 2021-07-08

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

| MOT expiry date | 2024-08-14 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 2 |
| Failed MOT tests | 1 |
| Total advice items | 1 |
| Total items failed | 1 |

| MOT #3 | 2023-08-10 08:47 |
|------------------|------------------|
| MOT test number | 706746322005 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-14 |

| Result | 99118186 X Failed |
|--|-----------------------------|
| | X Failed |
| Neareida Front Tyra has a cut in excess of the requirements doop enough to reach the ply or | |
| Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or (5.2.3 (d) (i)) Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | cords |

| MOT #1 | 2022-08-15 12:16 |
|-----------------|------------------|
| MOT test number | 113518790630 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/10



MB19CDK report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 14 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |
| | |

CarCheck.co.uk page 4/10




report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

| Date | |
|----------|--|
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |



Extra VOLKSWAGEN salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



Owner history

MB19CDK

report date: 2024-03-29

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report here.

More info >

Plate changes

More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Combact info | |

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 5 |
| First mileage registration | 2019-07-31 |
| Last registration | 2023-08-10 |
| Complete history | See info |



| Registration #1 | 2019-07-31 | 16 mi |
|-----------------|------------|-----------|
| Registration #2 | | 11.777 es |
| Registration #3 | 2022-08-15 | 13.294 mi |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.177 ms |

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

| 50225 | Air conditionir |
|-------|-----------------|
| 50295 | |
| 50482 | |
| 60501 | |
| 60566 | |
| 0567 | |
| 60569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 96% |
| Children | 85% |
| Pedestrian | 85% |
| Safety systems | 82% |
| Overall rating | 89% |
| Video | see crash video |



Dimensions & weight

| Width | 1871 mm |
|---------------------|---------|
| Height | 1450 mm |
| Length | 4862 mm |
| Wheel base | 2837 mm |
| Kerb weight | 1565 kg |
| Max. allowed weight | 2080 kg |

Additional information

| Fuel tank capacity | 66 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| CarChack co.uk | page 10/10 |

CarCheck.co.uk page 10/10

| Number of seats | 5 |
|-----------------|------------|
| Number of axles | 2 |
| Engine number | DADA658372 |