





report date: 2024-03-28

General information

Make	JAGUAR
Model	X-TYPE SE
Colour	Grey
Year of manufacture	-
Top speed	123 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	128 BHP
Max. torque	331 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	48.7 mpg



CarCheck.co.uk page 1/13



Internet history


Entry 2

Date 2021-12-11

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-11-10
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

Advice

Advice

MOT #19		2021-01-13 16:13
MOT test	number	574259370402
Result		✓ Passed
Next exp	iry date	2022-02-05
Advice	General under body corrosion	
Advice	Rear seat belts not checked as seats not in use	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.	14 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Minor (i))	Offside Front Side repeater lens defective which has no effect on emitted	light cracked (4.4.1 (b)
Advice	Engine cover fitted	
Advice	Small chip in windscreen	

Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

× Failed

MOT #18 2021-01-13 12:11

MOT test number 452348835262 Result

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Engine cover fitted Advice

Advice Small chip in windscreen

Offside Rear Direction indicator incorrect colour (4.4.3 (a)) MAJOR

MAJOR Offside Front Side repeater incorrect colour (4.4.3 (a))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice General under body corrosion

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Minor Offside Front Side repeater lens defective which has no effect on emitted light cracked (4.4.1 (b)

(i))

Advice Rear seat belts not checked as seats not in use

MAJOR Nearside Front Side repeater incorrect colour (4.4.3 (a))

2020-02-06 16:23 **MOT #17**

MOT test number 665995499587

Result Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Coil spring corroded (5.3.1 (b) (i))

Advice General under body corrosion

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 4/13



Result

AV54SRO report date: 2024-03-28

MOT #16 2019-01-15 07:35

MOT test number 747860789891

Result ✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #15 2019-01-10 16:50

MOT test number 367035391058

X Failed

MAJOR Rear Direction indicator incorrect colour both sides (4.4.3 (a))

Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MAJOR Offside Rear fog lamp does not emit a steady red light (4.5.4 (a))

Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) **MAJOR**

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14 2017-12-14 14:23

MOT test number 162238029638

Result ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

2016-12-20 16:05 **MOT #13**

MOT test number 966979142652

Result ✓ Passed

MOT #12 2015-12-18 12:53

MOT test number 197127225864

✓ Passed Result

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #11

MOT test number

666776125097

Result

MOT #10

2015-01-26 13:50

MOT test number

705086725046

Result

Pass with rectification

Nearside Registration plate lamp not working (1.1.C.1d)

MOT #9

MOT test number

Result

Notice Oil leak

2013-05-02 10:58

367212823136

✓ Passed

MOT test number

Result

Pass with rectification

Offside Rear Direction indicator incorrect colour (1.4.A.2f)

Pass with rectification

Nearside Rear Direction indicator incorrect colour (1.4.A.2f)

Notice

Oil leak

Pass with rectification

Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #7

MOT test number

798874941108

Result

Notice Air bag warning light on

CarCheck.co.uk page 6/13



MOT #3

AV54SRO

report date: 2024-03-28

2009-05-07 10:11

MOT #6		2011-05-24 16:59
MOT test number		259294041132
Result		X Failed
Pass with rectification	Nearside Rear position lamp(s) not working (1.1.A.3b)	
Notice Air bag warning	light on	

MOT #5	2010-05-17 11:25
MOT test number	951847730183
Result	✓ Passed
MOT #4	2010-05-13 13:45
MOT test number	813053830115
Result	X Failed
Fail Rear fog lamp emits a light other than red (1.3.2e)	
Fail Offside Rear Seat belt locking mechanism does not secure or release (5.2.5	a)

MOT test number	643037429161
Result	✓ Passed
MOT #2	2007-10-30 13:44
MOT test number	902893707324
Result	✓ Passed
MOT #1	2007-10-26 14:27
MOT test number	980889597283
Result	X Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)	
Onside Front Tyre dead depth below requirements of 1.0mm (4.1.E.1)	

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

e when misterly	
For how long did the current and previous owner(s) have this JAGUAR? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this JAGUAR had different number plates.	
Number of plates	,
Current registration	NK SIX
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2004-10-29
Last registration	2021-01-13
Complete history	See info



Registration #1	2004-10-29	8 mi
Registration #2	2007-10-26	38.178 mi
Registration #3	2007-10-30	38.178 mi
Registration #4	2009-05-07	58.830 mi
Registration #5	2010-05-13	67.985 mi
Registration #6	2010-05-17	67.986 mi
Registration #7	2011-05-24	73.987 mi
Registration #8	2013-05-02	87.136 mi
Registration #9	2015-01-26	88.522 mi
Registration #10	2015-12-18	88.541 mi
Registration #11		71.777 es
Registration #12		71.777 es
Registration #13		71.777 es
Registration #14		77.777 44
Registration #15		71.777 es
Registration #16		77.777 44
Registration #17		11.177 es
Registration #18		
Registration #16		

More info >

CarCheck.co.uk page 12/13



Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1789 mm
Height	1483 mm
Length	4716 mm
Wheel base	2710 mm
Max. allowed weight	2075 kg

Additional information

Fuel tank capacity	61 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0408311133336B

CarCheck.co.uk page 13/13