



HONDA

 **MK60JAO**


report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD I-VTEC ES
Colour	Silver
Year of manufacture	2010
Top speed	134 mph
0 - 60 mph	9.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H





## Internet history

### Entry 1

Date	2022-05-06
Pictures	50
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://cargurus.co.uk)



MOT history

MOT expiry date	2024-06-20
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	15
Total items failed	0

**MOT #12** 2023-06-16 12:16

**MOT test number** 117477360352

**Result** ✓ Passed

**Next expiry date** 2024-06-20

- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2022-06-21 10:03

**MOT test number** 700380751317

**Result** ✓ Passed

- Advice** Nearside Rear Nail in tyre
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner and outer edge (5.2.3 (e))



<b>MOT #10</b>	2022-06-20 11:36
<b>MOT test number</b>	516623869523
<b>Result</b>	✗ Failed
<b>MAJOR</b>	Nearside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
<b>MAJOR</b>	Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
<b>MAJOR</b>	Brake performance not tested (1.2.1 (g))
<b>Advice</b>	Nearside Rear Nail in tyre
<b>MAJOR</b>	Offside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))
<b>Advice</b>	Nearside Rear Tyre worn close to legal limit/worn on edge inner and outer edge (5.2.3 (e))
<b>MAJOR</b>	Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

<b>MOT #9</b>	2021-11-12 12:31
<b>MOT test number</b>	665119812656
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))
<b>Advice</b>	Rear Brake disc worn, pitted or scored, but not seriously weakened nearside and offside (1.1.14 (a) (ii))

<b>MOT #8</b>	2020-11-11 09:12
<b>MOT test number</b>	552677973333
<b>Result</b>	✓ Passed

<b>MOT #7</b>	2019-05-09 09:28
<b>MOT test number</b>	379658036283
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
<b>Advice</b>	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))



<b>MOT #6</b>	2018-05-09 11:10
<b>MOT test number</b>	909920508309
<b>Result</b>	✓ Passed
<b>MOT #5</b>	2017-05-15 13:46
<b>MOT test number</b>	199680000825
<b>Result</b>	✓ Passed
<b>MOT #4</b>	2016-05-17 07:41
<b>MOT test number</b>	788481554358
<b>Result</b>	✓ Passed
<b>MOT #3</b>	2015-11-12 11:38
<b>MOT test number</b>	356249645521
<b>Result</b>	✓ Passed
<b>MOT #2</b>	2014-11-20 10:56
<b>MOT test number</b>	385204124364
<b>Result</b>	✓ Passed
<b>MOT #1</b>	2013-11-21 14:56
<b>MOT test number</b>	987585723365
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 July 2024

✓  
**MOT**

**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



## Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

### Damage 1

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



### Damage 2

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



### Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start	End

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



**Finance check**

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled. If not, and you buy this HONDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this HONDA is financed.

<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



## Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	14
<b>First mileage registration</b>	2010-11-22
<b>Last registration</b>	2023-06-16
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2010-11-22	15 mi
<b>Registration #2</b>	2013-11-21	9.287 mi
<b>Registration #3</b>	2014-11-20	12.084 mi
<b>Registration #4</b>	2015-11-12	14.777 mi
<b>Registration #5</b>	2016-05-17	15.563 mi
<b>Registration #6</b>	2017-05-15	33.092 mi
<b>Registration #7</b>	2018-05-09	50.188 mi
<b>Registration #8</b>	2019-05-09	65.277 mi
<b>Registration #9</b>	2020-05-09	80.366 mi
<b>Registration #10</b>	2021-05-09	95.455 mi
<b>Registration #11</b>	2022-05-09	110.544 mi
<b>Registration #12</b>	2023-05-09	125.633 mi
<b>Registration #13</b>	2023-06-16	140.722 mi
<b>Registration #14</b>	2023-06-16	155.811 mi

[More info >](#)



## Safety ratings

<b>NCAP rating</b>	★★★★★
<b>Adult</b>	86%
<b>Children</b>	79%
<b>Pedestrian</b>	54%
<b>Safety systems</b>	86%
<b>Overall rating</b>	78%
<b>Video</b>	<a href="#">see crash video</a>



## Dimensions & weight

<b>Width</b>	1840 mm
<b>Height</b>	1440 mm
<b>Length</b>	4726 mm
<b>Wheel base</b>	2705 mm
<b>Kerb weight</b>	1414 kg

## Additional information

<b>Fuel tank capacity</b>	65 l
<b>Fuel delivery</b>	Multi-Point Injection
<b>Number of doors</b>	4
<b>Number of seats</b>	5
<b>Number of axles</b>	2
<b>Engine number</b>	R20A31103304