



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 SPORT D V50
Colour	Silver
Year of manufacture	2009
Top speed	127 mph
0 - 60 mph	9.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	49.6 mpg
CO2 emission	153 g/km
CO2 label	G






Internet history

Entry 1

Date	2022-04-23
Pictures	4
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	43
Total items failed	18

MOT #20	2024-03-27 15:23
---------	------------------

MOT test number	889451441859
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-03-29
------------------	------------

- Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge 205/50x17 (5.2.3 (e))
- Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Minor

Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #19**

2024-03-27 12:01

MOT test number

591013733347

Result

✗ Failed

Minor

Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge 205/50x17 (5.2.3 (e))

Fail

Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))

Advice

Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Minor

Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #18

2023-03-21 08:10

MOT test number

985868060006

Result

✓ Passed

MOT #17

2023-03-09 16:02

MOT test number

124781012123

Result

✗ Failed

Fail

Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))

Fail

Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

Fail

Exhaust emissions exceed default limit of 1.5m-1 (8.2.2.2 (b))

MOT #16

2022-03-30 07:37

MOT test number

881184431396

Result

✓ Passed

**MOT #15** 2022-03-28 15:37**MOT test number** 930688091079**Result** ✗ Failed**Fail** Brake lever has insufficient reserve travel (1.1.2 (a))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #14** 2020-10-16 08:26**MOT test number** 254444624757**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2020-10-14 14:09

MOT test number

278434946326

Result**✗ Failed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Side repeater not working (4.4.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MOT #12

2019-04-03 14:29

MOT test number

990122758098

Result**✓ Passed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11**

2019-04-03 09:24

MOT test number

785666447128

Result**✗ Failed**

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10

2018-04-18 15:01

MOT test number

594528738856

Result**✓ Passed**

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #9** 2018-04-18 09:27**MOT test number** 305533478855**Result** ✗ Failed**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #8** 2017-04-19 11:16**MOT test number** 196443000078**Result** ✓ Passed**MOT #7** 2016-01-27 09:26**MOT test number** 924003401287**Result** ✓ Passed**MOT #6** 2015-01-20 16:23**MOT test number** 165470625060**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #5** 2015-01-20 12:27**MOT test number** 315980025065**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-01-23 15:16**MOT test number** 525523824019**Result** ✓ Passed**MOT #3** 2014-01-22 09:34**MOT test number** 257642424071**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-01-22 09:19**MOT test number** 745392423058**Result** ✓ Passed**MOT #1** 2012-02-06 11:30**MOT test number** 796297932091**Result** ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
29 March 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2009-03-31
Last registration	2024-03-27
Complete history	See info



Registration #1	2009-03-31	9 mi
Registration #2	2012-02-06	22.457 mi
Registration #3	2013-01-22	33.082 mi
Registration #4	2014-01-22	47.740 mi
Registration #5	2014-01-23	47.740 mi
Registration #6	2015-01-20	63.259 mi
Registration #7	2015-01-20	63.259 mi
Registration #8	2016-01-27	72.659 mi
Registration #9	2017-04-19	80.288 mi
Registration #10	2018-04-18	92.790 mi
Registration #11	2018-04-18	92.790 mi
Registration #12	2019-04-18	105.290 mi
Registration #13	2019-04-18	105.290 mi
Registration #14	2019-04-18	105.290 mi
Registration #15	2019-04-18	105.290 mi
Registration #16	2019-04-18	105.290 mi
Registration #17	2019-04-18	105.290 mi
Registration #18	2019-04-18	105.290 mi
Registration #19	2019-04-18	105.290 mi
Registration #20	2019-04-18	105.290 mi
Registration #21	2019-04-18	105.290 mi
Registration #22	2019-04-18	105.290 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1489 kg
Max. allowed weight	1960 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	521737