





report date: 2024-03-29

General information

Make	KIA
Model	SORENTO CRDI KX-4 ISG
Colour	Grey
Year of manufacture	2016
Top speed	124 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	42.8 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-05-20

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



LG66DWE report date: 2024-03-29

MOT history

MOT expiry date	2024-05-21
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #6		2023-05-16 09:06
MOT test	number	207187205565
Result		✓ Passed
Next expir	ry date	2024-05-21
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Oil leak, but not excessive leaking from rear differential (8.4.1 (a) (i))	

MOT #5	2022-05-14 09:59
MOT test number	446802612636
Result	✓ Passed
Advice Nearside Rear Suspension arm pin or bush worn but not resulting in e arm bush cracked (5.3.4 (a) (i)) Advice Slight oil leak diff	xcessive movement trailing
Advice Offside Rear Suspension arm pin or bush worn but not resulting in excarm bush cracked (5.3.4 (a) (i))	cessive movement trailing

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #4 2021-05-22 08:32

MOT test number 954694111534

Result
✓ Passed

MOT #3 2020-08-17 11:12

MOT test number 762286537600

Result ✓ Passed

MOT #2 2019-10-10 15:30

MOT test number 947118415013

Result
✓ Passed

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #1 2019-10-10 12:03

MOT test number 296836538952

Result X Failed

Fail Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	21 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report I	
THE STATE OF THE S	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	mn.n.n
Current registration	OK SIES
Plate since	
	More info >

CarCheck.co.uk page 8/11



LG66DWE report date: 2024-03-29

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



LG66DWE report date: 2024-03-29

Mileage check

Odometer	In miles
Odollietei	III IIIIIES
Mileage registrations	8
First mileage registration	2016-09-07
Last registration	2023-05-16
Complete history	See info



Registration #1	2016-09-07	16 mi
Registration #2	2019-10-10	62.834 mi
Registration #3	2019-10-10	62.834 mi
Registration #4	2020-08-17	73.429 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

page 10/11 CarCheck.co.uk



LG66DWE report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1685 mm
Length	4780 mm
Wheel base	2780 mm
Kerb weight	1885 kg
Max. allowed weight	2620 kg

Additional information

Fuel tank capacity	71
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/1:

Number of axles 2

Engine number D4HBGH266562