



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	I40 CRDI ACTIVE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	119 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	113 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-06-20
Pictures	8
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2025-02-10
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	36
Total items failed	5

MOT #12	2024-02-11 16:09
MOT test number	445225736859
Result	✓ Passed
Next expiry date	2025-02-10
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened o/s, n/s (1.1.14 (a) (ii))

MOT #11	2024-02-10 17:09
MOT test number	342763040014
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened o/s, n/s (1.1.14 (a) (ii))
Fail	Nearside Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))

MOT #10	2022-11-04 17:51
MOT test number	279637317719
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #9** 2022-11-04 17:51**MOT test number** 696514400371**Result** ✗ Failed**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2021-10-25 09:43**MOT test number** 282453269072**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2021-07-21 08:17**MOT test number** 224082878559**Result** ✓ Passed**Minor** Offside Front Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Advice** Offside Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #6** 2020-07-21 09:40**MOT test number** 617706439667**Result** ✓ Passed

**MOT #5** 2019-07-25 10:16**MOT test number** 583300526897**Result** ✓ Passed

- Advice** Difficult to select gears
- Advice** Corrosion to exhaust
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Engine cover fitted

MOT #4 2019-07-25 09:24**MOT test number** 257596346528**Result** ✗ Failed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Engine cover fitted
- Advice** Corrosion to exhaust
- Advice** Difficult to select gears
- Advice** N/s/f wiper is smearing
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #3 2018-07-19 15:23**MOT test number** 780930048850**Result** ✓ Passed

- Advice** Engine cover fitted
- Advice** Emissions are too low to test
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Both front wipers are smearing
- Advice** Undertray fitted



MOT #2	2018-07-19 08:15
MOT test number	192395690950
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Both front wipers are smearing
Fail	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Undertray fitted
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Engine cover fitted
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Emissions are too low to test

MOT #1	2017-07-19 10:11
MOT test number	768357475527
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
10 February 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-07-24
Last registration	2024-02-11
Complete history	See info



Registration #1	2014-07-24	19 mi
Registration #2	2017-07-19	37.683 mi
Registration #3	2018-07-19	47.364 mi
Registration #4	2018-07-19	47.364 mi
Registration #5	2019-07-25	57.751 mi
Registration #6	2019-07-25	57.751 mi
Registration #7	2020-07-21	71.714 mi
Registration #8	2020-07-21	71.714 mi
Registration #9	2020-07-21	71.714 mi
Registration #10	2020-07-21	71.714 mi
Registration #11	2020-07-21	71.714 mi
Registration #12	2020-07-21	71.714 mi
Registration #13	2020-07-21	71.714 mi
Registration #14	2020-07-21	71.714 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4740 mm
Wheel base	2770 mm
Kerb weight	1601 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	D4FDEU439856