



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM
Colour	Grey
Year of manufacture	2010
Top speed	135 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	300 Nm at 4.000 rpm
Engine capacity	1.976 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.9 mpg
CO2 emission	189 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-09-19
Pictures	9
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-23
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	27
Total items failed	5

MOT #14	2023-10-24 13:49
MOT test number	281951444572
Result	✓ Passed
Next expiry date	2024-10-23
Advice	Nearside Front Brake disc worn, but not excessively lip (1.1.14 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened lip (1.1.14 (a) (ii))

MOT #13	2022-09-06 14:10
MOT test number	167283764914
Result	✓ Passed
Advice	Suspension arm pin or bush worn but not resulting in excessive movement both rear trailing arm bushes (5.3.4 (a) (i))

MOT #12	2022-09-06 07:46
MOT test number	964018494012
Result	✗ Failed
Fail	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #11	2021-09-27 15:39
MOT test number	433282389338
Result	✓ Passed



MOT #10	2021-09-27 15:39
MOT test number	285381709506
Result	✗ Failed
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9	2020-09-15 10:00
MOT test number	599621258001
Result	✓ Passed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn inner-outer edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear suspension arms bushes slightly deteriorated
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn inner-outer edge (5.2.3 (e))

MOT #8	2020-09-15 10:00
MOT test number	493001725579
Result	✗ Failed
Advice	Rear suspension arms bushes slightly deteriorated
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn inner-outer edge (5.2.3 (e))
Pass with rectification	Nearside Headlamp aim too low (4.1.2 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn inner-outer edge (5.2.3 (e))
Pass with rectification	Offside Headlamp aim too low (4.1.2 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7** 2019-09-09 10:48**MOT test number** 571974005282**Result** ✓ Passed**Advice** Offside rear tyre perished**Advice** Nearside rear tyre has cut in tread, perished**MOT #6** 2018-09-10 09:44**MOT test number** 182850250036**Result** ✓ Passed**Advice** Rear registration plate delaminated**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Outer cv boot deteriorated**MOT #5** 2017-09-15 09:14**MOT test number** 543800754710**Result** ✓ Passed**Advice** Front Brake pad(s) modified but not seriously weakened (3.5.1n)**MOT #4** 2016-09-27 09:08**MOT test number** 802178390310**Result** ✓ Passed**Advice** Engine covers & under trays fitted obscuring the view to some components**Advice** Oil leak engine - further investigation advised**Advice** Child Seat fitted not allowing full inspection of adult belt Across 3 rear seats and far O/S/R seat**Advice** Items removed from driver's view prior to test



MOT #3 2016-09-27 08:24

MOT test number 513153668587

Result ✗ Failed

- Advice** Oil leak engine - further investigation advised
- Advice** Child Seat fitted not allowing full inspection of adult belt Across 3 rear seats and far O/S/R seat
- Advice** Items removed from driver's view prior to test
- Advice** Engine covers & under trays fitted obscuring the view to some components
- Fail** Windscreen wiper does not clear the windscreen effectively Both fronts (8.2.2)

MOT #2 2015-09-30 09:55

MOT test number 511947246748

Result ✓ Passed

MOT #1 2013-08-21 14:49

MOT test number 255023633272

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
23 October 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX60WJF
Plate since	2019-09-29
Current registration	EX60WJF
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-09-01
Last registration	2023-10-24
Complete history	See info



Registration #1	2010-09-01	13 mi
Registration #2	2013-08-21	25.969 mi
Registration #3	2015-09-30	43.590 mi
Registration #4	2016-09-27	54.884 mi
Registration #5	2016-09-27	54.891 mi
Registration #6	2017-09-15	64.359 mi
Registration #7	2018-09-10	73.161 mi
Registration #8	2019-09-09	83.896 mi
Registration #9	2020-09-09	95.377 mi
Registration #10	2021-09-09	107.377 mi
Registration #11	2022-09-09	119.377 mi
Registration #12	2023-09-09	131.377 mi
Registration #13	2024-09-09	143.377 mi
Registration #14	2025-09-09	155.377 mi
Registration #15	2026-09-09	167.377 mi
Registration #16	2027-09-09	179.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1697 kg
Max. allowed weight	2450 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	AP42778