



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T2
Colour	Silver
Year of manufacture	2006
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-02-05
Pictures	8
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-12-06
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	28
Total items failed	16

MOT #22 2023-12-07 09:20

MOT test number 707825568008

Result ✓ Passed

Next expiry date 2024-12-06

Minor Brake hose slightly chafed both front (1.1.12 (b) (i))

Advice Both front headlamps little misty

MOT #21 2022-12-06 09:35

MOT test number 383785068158

Result ✓ Passed

Advice Offside Front Play in steering rack inner joint(s)

MOT #20 2021-12-03 11:45

MOT test number 293635128995

Result ✓ Passed

Minor Offside Front Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #19** 2020-12-02 08:01**MOT test number** 765604667737**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #18** 2019-05-25 08:37**MOT test number** 639140238415**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear light unit crackes**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #17** 2019-05-25 08:37**MOT test number** 866851352282**Result** ✗ Failed**Pass with rectification** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Nearside Rear light unit crackes**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #16** 2018-05-12 10:34**MOT test number** 970634232354**Result** ✓ Passed

**MOT #15** 2018-05-12 09:13**MOT test number** 801522697411**Result** ✗ Failed**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #14** 2017-05-23 14:36**MOT test number** 968648566570**Result** ✓ Passed**MOT #13** 2017-05-23 09:41**MOT test number** 701725927738**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Brake pedal spongy (3.3.B.1b)**MOT #12** 2016-05-20 09:20**MOT test number** 131441221427**Result** ✓ Passed**MOT #11** 2015-05-20 13:48**MOT test number** 348500145107**Result** ✓ Passed

**MOT #10**

2015-05-20 10:33

MOT test number

336980545160

Result**✗ Failed****Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Nearside front tyre worn on edges**Notice** Front discs lipped**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Rear tyres worn on edges**MOT #9**

2014-05-22 10:38

MOT test number

217302644461

Result**✓ Passed****MOT #8**

2014-05-21 12:30

MOT test number

405801844196

Result**✗ Failed****Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front Seat belt retracting mechanism defective (5.2.5b)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2013-05-23 11:05**MOT test number** 366993243104**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2012-05-15 12:48**MOT test number** 669556432198**Result** ✓ Passed**Notice** Front brake pads worn**MOT #5** 2011-05-12 12:05**MOT test number** 495222931186**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Oil level low**MOT #4** 2010-05-28 11:04**MOT test number** 730088540175**Result** ✓ Passed**MOT #3** 2010-05-19 12:22**MOT test number** 193809130176**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)



MOT #2	2009-05-22 11:58
MOT test number	282562649480
Result	✓ Passed

MOT #1	2009-05-22 11:58
MOT test number	414772149160
Result	✗ Failed
Pass with rectification	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
6 December 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	6 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2006-05-25
Last registration	2023-12-07
Complete history	See info



Registration #1	2006-05-25	29 mi
Registration #2	2009-05-22	36.269 mi
Registration #3	2010-05-19	49.877 mi
Registration #4	2010-05-28	50.245 mi
Registration #5	2011-05-12	64.713 mi
Registration #6	2012-05-15	77.984 mi
Registration #7	2013-05-23	89.972 mi
Registration #8	2014-05-21	105.481 mi
Registration #9	2014-05-22	105.481 mi
Registration #10	2015-05-20	121.227 mi
Registration #11	2015-05-20	121.227 mi
Registration #12	2016-05-20	135.254 mi
Registration #13	2016-05-20	135.254 mi
Registration #14	2016-05-20	135.254 mi
Registration #15	2016-05-20	135.254 mi
Registration #16	2016-05-20	135.254 mi
Registration #17	2016-05-20	135.254 mi
Registration #18	2016-05-20	135.254 mi
Registration #19	2016-05-20	135.254 mi
Registration #20	2016-05-20	135.254 mi
Registration #21	2016-05-20	135.254 mi
Registration #22	2016-05-20	135.254 mi
Registration #23	2016-05-20	135.254 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD5091090