




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	PASSAT GT TDI (170BHP)
Colour	Black
Year of manufacture	2006
Top speed	136 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	46.3 mpg
CO2 emission	156 g/km
CO2 label	G








Internet history

Entry 1

Date	2021-06-04
Pictures	29
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-05-19
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	25
Total items failed	2

MOT #13	2022-05-17 12:17
MOT test number	559679606906
Result	✓ Passed
Next expiry date	2023-05-19
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Nearside side repeater in mirror unit deteriorating
Advice	Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))

**MOT #12** 2022-05-16 09:31**MOT test number** 681635475713**Result** ✗ Failed**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**Advice** Nearside side repeater in mirror unit deteriorating**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**Fail** Nearside Rear Suspension arm pin or bush excessively worn Trail arm bush (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge Worn on inner edge (5.2.3 (e))**MOT #11** 2021-05-20 13:16**MOT test number** 958140037351**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #10** 2020-06-24 15:43**MOT test number** 130418165850**Result** ✓ Passed**Advice** Front no plate poor**Advice** Steel wheel fitted to nsr

**MOT #9**

2019-06-26 09:59

MOT test number

816482049884

Result

✓ Passed

Advice Nsf strut top mount noisy**Advice** Rear pads getting low**Advice** Front no plate poor**MOT #8**

2018-07-10 11:19

MOT test number

976678053553

Result

✓ Passed

Advice Front registration plate poor**Advice** Nearside rear foremost lower arm bushes worn**Advice** Nearside front tyre worn and cut on inner edge**Advice** Offside front drop link covers poor**MOT #7**

2017-06-16 14:00

MOT test number

721211775113

Result

✓ Passed

Advice Front plate faded n/s/r trailing arm bush play**MOT #6**

2016-05-20 09:26

MOT test number

308839652938

Result

✓ Passed

Advice NSR TYRE WORN ON EDGE**Advice** UNDERNEATH DAMP WITH FUEL



MOT #5	2015-05-28 11:39
---------------	------------------

MOT test number	899778945178
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-07-03 12:32
---------------	------------------

MOT test number	328514483183
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-06-08 16:51
---------------	------------------

MOT test number	287270162133
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)
---------------	---

MOT #2	2011-06-06 13:36
---------------	------------------

MOT test number	945227051155
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

MOT #1	2010-02-02 17:00
---------------	------------------

MOT test number	123873030458
------------------------	--------------

Result	✓ Passed
---------------	----------



Tax & MOT check

X

Untaxed

Tax expired:
1 April 2023

X

MOT

Expired:
19 May 2023

Tax status	Expired at 1 April 2023
Days left	395 days too late
MOT expiry date	19 May 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 WR56UCG
Plate since	2019-06-29
Current registration	 WR56UCG
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2006-12-15
Last registration	2022-05-17
Complete history	See info



Registration #1	2006-12-15	24 mi
Registration #2	2010-02-02	35.216 mi
Registration #3	2011-06-06	50.128 mi
Registration #4	2012-06-08	61.422 mi
Registration #5	2013-07-03	75.775 mi
Registration #6	2015-05-28	101.733 mi
Registration #7	2016-05-20	114.047 mi
Registration #8	2017-06-16	131.361 mi
Registration #9	2018-06-16	148.675 mi
Registration #10	2019-06-16	165.989 mi
Registration #11	2020-06-16	183.303 mi
Registration #12	2021-06-16	200.617 mi
Registration #13	2022-05-17	217.931 mi
Registration #14	2023-05-17	235.245 mi
Registration #15	2024-03-28	252.559 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1479 mm
Length	4204 mm
Wheel base	2578 mm
Kerb weight	1445 kg
Max. allowed weight	1910 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BMN025085