



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-09-15
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-12
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	22
Total items failed	9

MOT #16	2023-12-04 15:46
MOT test number	752923380489
Result	✓ Passed
Next expiry date	2024-12-12

MOT #15	2022-12-13 16:00
MOT test number	568927180358
Result	✓ Passed

MOT #14	2022-12-13 10:52
MOT test number	612279751796
Result	✗ Failed

Fail Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #13	2022-12-05 13:13
MOT test number	553612977908
Result	✓ Passed

MOT #12	2022-09-02 14:46
MOT test number	456558905863
Result	✓ Passed

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt



MOT #11	2021-09-17 19:29
MOT test number	986361176098
Result	✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #10	2021-09-17 19:28
MOT test number	573486739901
Result	✗ Failed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Pass with rectification	Registration plate lamp missing in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Pass with rectification	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Pass with rectification	Windscreen washer not working (3.5 (a))

MOT #9	2020-10-26 09:39
MOT test number	541810934780
Result	✓ Passed

MOT #8	2019-05-21 15:27
MOT test number	365435283674
Result	✓ Passed
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Brake disc worn, pitted or scored, but not seriously weakened front and rear brake discs borderline pass on m o t strongly recommend replacement a s a p (1.1.14 (a) (ii))

**MOT #7** 2019-05-21 10:16**MOT test number** 675598926939**Result** ✗ Failed

Advice Brake disc worn, pitted or scored, but not seriously weakened front and rear brake discs
borderline pass on m o t strongly recommend replacement a s a p (1.1.14 (a) (ii))

Fail Offside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Fail Nearside Rear Seat belt buckle not functioning as intended latch not working (7.1.2 (d))

Fail Windscreen washer provides insufficient washer liquid pump pressure not there washer bottle is
leaking under wing when washers are operated (3.5 (a))

MOT #6 2018-05-02 16:25**MOT test number** 759004749263**Result** ✓ Passed

Advice Front Tyre worn close to the legal limit Both Tyre Inner edge (4.1.E.1)

Advice Under-trays fitted obscuring some underside components

MOT #5 2018-05-02 14:10**MOT test number** 982234767059**Result** ✗ Failed

Fail Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Under-trays fitted obscuring some underside components

Advice Front Tyre worn close to the legal limit Both Tyre Inner edge (4.1.E.1)

Fail Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #4** 2017-05-13 10:28**MOT test number** 135964939823**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Oil leak**MOT #3** 2016-05-07 11:51**MOT test number** 923843099618**Result** ✓ Passed**Advice** Advise: engine covers fitted obscuring some items.**Advice** Advise: under trays fitted obscuring some items.**MOT #2** 2015-05-16 09:21**MOT test number** 735416535151**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #1** 2015-04-15 08:59**MOT test number** 885525905177**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
12 December 2024

Tax status	Valid until 1 November
Days left	186
MOT expiry date	12 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2012-05-11
Last registration	2023-12-04
Complete history	See info



Registration #1	2012-05-11	12 mi
Registration #2	2015-04-15	84.829 mi
Registration #3	2015-05-16	86.667 mi
Registration #4	2016-05-07	96.026 mi
Registration #5	2017-05-13	109.090 mi
Registration #6	2018-05-02	117.218 mi
Registration #7	2018-05-02	117.218 mi
Registration #8	2019-05-21	122.580 mi
Registration #9	2019-05-21	122.580 mi
Registration #10	2020-05-20	125.277 mi
Registration #11	2020-05-20	125.277 mi
Registration #12	2020-05-20	125.277 mi
Registration #13	2020-05-20	125.277 mi
Registration #14	2020-05-20	125.277 mi
Registration #15	2020-05-20	125.277 mi
Registration #16	2020-05-20	125.277 mi
Registration #17	2020-05-20	125.277 mi
Registration #18	2020-05-20	125.277 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDCU154091