





report date: 2024-03-29

## General information

Make	CITROEN
Model	RELAY 35 L2 HDI
Colour	White
Year of manufacture	2014
Top speed	96 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	32.5 mpg
CO2 emission	229 g/km
CO2 label	L



CarCheck.co.uk page 1/12



## Internet history

### Entry 1

 Date
 2022-02-20

 Pictures
 2

Listing price <u>View report</u>





source: cargurus.co.uk

CarCheck.co.uk page 2/12



LG14ZVX

report date: 2024-03-29

# MOT history

MOT expiry date	2024-04-16
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	25
Total items failed	0

MOT #7	2023-04-17 12:43
MOT test number	838686514852
Result	✓ Passed
Next expiry date	2024-04-16
Minor Nearside Front Lower Suspension arm ball joint dust cover severely dete	riorated (5.3.4 (b) (i))
Advice Play in steering rack inner joint(s)	
Advice Brakes imbalanced requirements only just met. It would appear that the adjustment or repair. Front and rear (1.2.1 (b) (i))	e braking system requires

MOT #6	2022-04-11 09:33
MOT test	<b>number</b> 867836724186
Result	✓ Passed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4
Advice	Offside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

CarCheck.co.uk page 3/12



LG14ZVX

report date: 2024-03-29

MOT #5 2022-03-31 08:35

**MOT test number** 567554745499

Result X Failed

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

(i))

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MAJOR** Front Registration plate inscription illegible (0.1 (b))

**MAJOR** Offside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Front Inner Drag link end ball joint has slight play (2.1.3 (b) (i))

MAJOR Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MAJOR Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))

Minor Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #4** 2021-01-19 11:45

**MOT test number** 654943247611

**Advice** Offside Front Sub-frame ball joint has slight play (5.3.4 (a) (i))

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Offside Front Anti-roll bar modified but not seriously weakened (5.3.3 (c) (i))

Advice Nearside Front Sub-frame ball joint has slight play (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar modified but not seriously weakened (5.3.3 (c) (i))

CarCheck.co.uk page 4/12



MOT #3 2019-05-23 09:10

**MOT test number** 667457839102

**Result** ✓ Passed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #2 2018-05-25 14:33

**MOT test number** 398793957787

Result \rightarrow Passed

MOT #1 2017-05-25 13:09

**MOT test number** 545283771574

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	16 April 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	HK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



LG14ZVX

report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-06-03
Last registration	2023-04-17
Complete history	See info



Registration #1	2014-06-03	29 mi
Registration #2	2017-05-25	124.595 mi
Registration #3	2018-05-25	175.567 mi
Registration #4	2019-05-23	220.362 mi
Registration #5	2021-01-19	261.204 mi
Registration #6		11.777 ea
Registration #7		0.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



# Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	TRJA0767555

CarCheck.co.uk page 12/12