



report date: 2024-03-29

General information

Make	VOLVO
Model	V50 D3 SE
Colour	Silver
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	400 Nm at 1.400 rpm
Cylinders	5
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.9 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2022-04-21
Pictures	8
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #13	2022-04-22 14:41
MOT test number	561275916301
Result	✓ Passed
Next expiry date	2023-04-21

MOT #12	2022-04-21 14:52
MOT test number	801189340907
Result	✗ Failed

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

MOT #11	2021-08-19 07:15
MOT test number	893827742811
Result	✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear subframe rusty

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice O/s/r tyre going lumpy

Advice Front subframe rusty

MOT #10	2020-08-18 15:47
MOT test number	704044783559
Result	✓ Passed

Advice Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #9** 2020-08-18 14:48**MOT test number** 405216786261**Result** ✗ Failed**Fail** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**Minor** Nearside Rear Upper Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))**MOT #8** 2019-08-21 14:46**MOT test number** 171183760732**Result** ✓ Passed**Advice** O/S/F tyre inner edge wearing thin**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**MOT #7** 2019-08-21 14:46**MOT test number** 191700160634**Result** ✗ Failed**Pass with rectification** Headlamp aim too low (4.1.2 (a))**Advice** O/S/F tyre inner edge wearing thin**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))**MOT #6** 2018-08-22 13:52**MOT test number** 488228362647**Result** ✓ Passed

**MOT #5** 2017-08-21 09:33**MOT test number** 824296749971**Result** ✓ Passed**Advice** Nearside Front tyre has cut in outer sidewall.**MOT #4** 2016-08-15 12:26**MOT test number** 920170593161**Result** ✓ Passed**Advice** Offside Rear Outer Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Upper bump stop worn/split**Advice** Nearside Rear Outer Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear brake binding slightly**Advice** Nearside Rear Upper bump stop worn/split**MOT #3** 2015-08-27 08:31**MOT test number** 270110509265**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2014-08-18 12:55**MOT test number** 289740134228**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2013-08-27 12:17
MOT test number	259889133255
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX60VBM
Plate since	2019-03-29
Current registration	YX60VBM
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-09-03
Last registration	2022-04-22
Complete history	See info



Registration #1	2010-09-03	25 mi
Registration #2	2013-08-27	27.758 mi
Registration #3	2014-08-18	36.814 mi
Registration #4	2015-08-27	46.351 mi
Registration #5	2016-08-15	56.765 mi
Registration #6	2017-08-21	66.122 mi
Registration #7	2018-08-22	74.322 mi
Registration #8	2019-08-21	83.101 mi
Registration #9	2020-08-21	91.880 mi
Registration #10	2021-08-21	100.659 mi
Registration #11	2022-04-22	109.438 mi
Registration #12	2023-04-22	118.217 mi
Registration #13	2024-03-29	126.996 mi
Registration #14	2025-03-29	135.775 mi
Registration #15	2026-03-29	144.554 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1861 mm
Height	1493 mm
Length	4851 mm
Wheel base	2835 mm
Kerb weight	1684 kg
Max. allowed weight	2200 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	882769