





General information

| Make | MERCEDES-BENZ |
|---------------------|---------------------|
| Model | ML ML250 BLUETEC SE |
| Colour | White |
| Year of manufacture | 2013 |
| Top speed | 130 mph |
| 0 - 100 km/h | 9.0 seconds |
| 0 - 60 mph | 9.0 seconds |
| Gearbox | 7 speed automatic |

Engine & fuel consumption

| Power | 150 kW / 204 HP / 204 BHP |
|-------------------------|---------------------------|
| Max. torque | 500 Nm at 1.800 rpm |
| Engine capacity | 2.143 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 38.7 mpg |
| Consumption extra urban | 50.4 mpg |
| Consumption combined | 44.8 mpg |
| CO2 emission | 165 g/km |
| CO2 label | G |







Internet history

Entry 1

Date

Pictures

2022-04-06

37

Listing price

View report



source: cargurus.co.uk



MOT history

| MOT expiry date | 2024-08-09 |
|--------------------|------------|
| MOT pass rate | 90 % |
| MOT passed | 9 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 2 |

| MOT #10 | 2023-08-10 10:43 |
|------------------|------------------|
| MOT test number | 535834558615 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-09 |

| MOT #9 | | 2023-08-07 12:00 |
|--------|---|------------------|
| MOT te | st number | 407287155661 |
| Result | | 🗙 Failed |
| Fail | Offside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Fail | Offside Front Coil spring fractured or broken (5.3.1 (b) (i)) | |

| MOT #8 | 2022-10-05 11:46 |
|-----------------|------------------|
| MOT test number | 371155233709 |
| Result | ✓ Passed |
| | |

| MOT #7 | | 2022-04-03 07:01 |
|----------|--|------------------|
| MOT test | number | 262650337866 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Rear Inner Brake pad(s) wearing thin both sides (1.1.13 (a) (ii)) | |





| МОТ #6 | 2021-08-17 13:06 |
|--|------------------|
| MOT test number | 356700126143 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2020-08-24 08:53 |
| MOT test number | 468508517378 |
| Result | ✓ Passed |
| Advice Offside Front tyre starting to wear on edges | |
| Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords outer side wall (5.2.3 (d) (i)) | |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #4 | 2019-09-16 09:13 |
|----------|---|
| MOT test | number 194144653872 |
| Result | ✓ Passed |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge wearing on inner edges (5.2.3 (e)) |
| Advice | Items removed from driver's view prior to test |

| MOT #3 | | 2018-09-18 08:35 |
|----------|--|------------------|
| MOT test | number | 890929415292 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #2 | 2017-09-23 11:40 |
|-----------------|------------------|
| MOT test number | 950642697376 |
| Result | ✓ Passed |





| MOT #1 | 2016-09-23 14:57 |
|--|------------------|
| MOT test number | 848952903404 |
| Result | ✓ Passed |
| Advice Offside Rear parking brake slightly binding | |





Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------------------------------------|
| Date | FERRE |
| Category | A PLANE |
| Туре | |
| Damage 2 | AMPLE |
| | A A A A A A A A A A A A A A A A A A A |
| Date | 1. E |
| Category | ant |
| Туре | |

Extra MERCEDES-BENZ salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| 2000000 | |
|--|-------------|
| | |
| ******* | |
| | |
| And a second sec | |
| ********** | |
| ******** | |
| | |
| | More info > |
| Plate changes | |
| See in this check if this MERCEDES-BENZ had different number plates. | |
| Number of plates | , |
| Current registration | |
| | |
| Plate since | |
| Plate since Correct registration | |
| Plate since Correct registration Plate since | 1111-23-23 |





Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 12 |
| First mileage registration | 2013-09-28 |
| Last registration | 2023-08-10 |
| Complete history | See info |



| Registration #1 | 2013-09-28 | 9 mi |
|------------------------------------|------------|---|
| Registration #2 | 2016-09-23 | 51.629 mi |
| Registration #3 | 2017-09-23 | 57.278 mi |
| Registration #4 | 2018-09-18 | 63.459 mi |
| Registration #5 | 2019-09-16 | 73.200 mi |
| Registration #6 | 2020-08-24 | 80.951 mi |
| | | |
| Registration #7 | | 11.777 mi |
| Registration #7 Registration #8 | | 10.000 est |
| - | | 00.000 est 00.000 est 00.000 est |
| Registration #8 | | 00.000 est 00.000 est 00.000 est 00.000 est |
| Registration #8 Registration #9 | | 00.000 est 0.000 est 00.000 est 00.000 est 00.000 est |

More info \rightarrow





Car features

| S0225 | Air conditioning |
|--------|------------------|
| S0295 | |
| 50482 | |
| \$0501 | |
| \$0566 | |
| \$0567 | |
| S0569 | |

Dimensions & weight

| Width | 1998 mm |
|---------------------|---------|
| Height | 1796 mm |
| Length | 4804 mm |
| Wheel base | 2915 mm |
| Kerb weight | 2150 kg |
| Max. allowed weight | 2950 kg |

Additional information

| Fuel tank capacity | 70 |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 65196031474778 |