



General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2008
Top speed	122 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 2

Date	2022-12-09
Pictures	17
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-04
Pictures	14
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-12-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	21
Total items failed	18

MOT #16	2023-12-05 15:23
MOT test number	598745123637
Result	✓ Passed
Next expiry date	2024-12-04
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Upper Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Upper Coil spring corroded (5.3.1 (b) (i))

**MOT #15**

2023-12-01 11:44

**MOT test number**

248912313553

**Result****✗ Failed**

**Fail** Nearside Rear Suspension arm corroded and seriously weakened Rear arm that seats the coil spring, marked with yellow chalk (5.3.3 (b) (i))

**Advice** Nearside Rear Brake cable damaged but not to excess (1.1.15 (a))

**Fail** Offside Rear Brake pipe likely to become detached or damaged Insecure, Bracket that secures hand brake cable and brake pipe has not been secure to fixing (missing bolt) (1.1.11 (d) (ii))

**Fail** Offside Rear Brake cable insecure Cable hanging low (1.1.15 (c))

**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))

**Advice** Offside Front Upper Coil spring corroded (5.3.1 (b) (i))

**Fail** Offside Rear Suspension arm corroded and seriously weakened Rear arm that seats the coil spring, marked with yellow chalk (5.3.3 (b) (i))

**Fail** Nearside Rear Brake pipe likely to become detached or damaged Insecure, Bracket that secures hand brake cable and brake pipe has not been secure to fixing (missing bolt) (1.1.11 (d) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Brake cable damaged but not to excess (1.1.15 (a))

**Advice** Exhaust heat shield insecure

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**Advice** Nearside Front Upper Coil spring corroded (5.3.1 (b) (i))

**MOT #14**

2022-12-02 09:30

**MOT test number**

927757995404

**Result****✓ Passed**

**MOT #13**

2022-11-23 16:46

**MOT test number**

110739738311

**Result**

✗ Failed

- Fail** Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Brake lining(s) less than 1.5 mm thick both rears (1.1.13 (a) (ii))
- Fail** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**MOT #12**

2021-05-26 13:22

**MOT test number**

163924490097

**Result**

✓ Passed

**MOT #11**

2021-05-17 14:39

**MOT test number**

908928794604

**Result**

✗ Failed

- Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #10**

2020-06-23 09:24

**MOT test number**

723904695676

**Result**

✓ Passed

- Advice** Offside Rear tyre tread getting low and cracked

**MOT #9** 2019-06-26 09:45**MOT test number** 461703313026**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-06-13 09:44**MOT test number** 308719233754**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2017-06-26 09:56**MOT test number** 199067735186**Result** ✓ Passed**MOT #6** 2016-06-22 09:29**MOT test number** 237655896322**Result** ✓ Passed**MOT #5** 2015-06-23 14:30**MOT test number** 236484475180**Result** ✓ Passed

**MOT #4** 2015-06-22 11:47**MOT test number** 847473275117**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Offside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Rear Trailing arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

**MOT #3** 2014-06-24 10:14**MOT test number** 396465974126**Result** ✓ Passed

- Notice** N/s and o/s rear trailing arm bushes split
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2013-06-25 09:21**MOT test number** 259766973176**Result** ✓ Passed

- Notice** Slight cut to near side rear outter tyre wall

**MOT #1** 2012-06-11 09:10**MOT test number** 875053662154**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
4 December 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	4 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-07-11
Last registration	2023-12-05
Complete history	<a href="#">See info</a>



Registration #1	2008-07-11	6 mi
Registration #2	2012-06-11	33.265 mi
Registration #3	2013-06-25	42.799 mi
Registration #4	2014-06-24	49.070 mi
Registration #5	2015-06-22	55.583 mi
Registration #6	2015-06-23	55.590 mi
Registration #7	2016-06-22	63.804 mi
Registration #8	2017-06-26	73.055 mi
Registration #9	2018-06-13	81.313 mi
Registration #10	2019-06-26	89.171 mi
Registration #11	2020-06-22	95.377 mi
Registration #12	2021-06-22	101.583 mi
Registration #13	2022-06-22	107.789 mi
Registration #14	2023-06-22	113.995 mi
Registration #15	2023-06-22	120.201 mi
Registration #16	2023-06-22	126.407 mi
Registration #17	2023-06-22	132.613 mi
Registration #18	2023-06-22	138.819 mi
Registration #19	2023-06-22	145.025 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	8A56984