



FVIOGZS

report date: 2024-03-28

General information

Make	FORD
Model	FUSION ZETEC
Colour	Grey
Year of manufacture	-
Top speed	101 mph
0 - 60 mph	13.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	78 BHP
Max. torque	124 Nm at 3.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	33.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	43.5 mpg





Internet history

Entry 1

Date	2021-06-10
Pictures	1
Listing price	View report

AA

This dealer has signed up to our **Dealer Promise.**

- Free history check
- 6 months (minimum) MOT
- Free 12 months Breakdown cover

aacars.com

source: [autotrader.co.uk](#)



MOT history

MOT #14	2021-04-09 15:28
MOT test number	551998955213
Result	✓ Passed
Next expiry date	2022-04-08

MOT #13	2021-04-09 08:13
MOT test number	918591760901
Result	✗ Failed

- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Fail** Nearside Front Headlamp aim not tested (4.1.2 (b))

MOT #12	2020-03-25 10:43
MOT test number	398861205334
Result	✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake pipe slightly damaged (1.1.11 (c))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2019-03-27 14:38
MOT test number	427222233032
Result	✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Wear in both front brake discs

**MOT #10**

2019-03-26 16:47

MOT test number

728328425933

Result**✗ Failed****Fail** Horn sound not in accordance with requirements (7.7 (c))**Minor** Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Wear in both front brake discs**Fail** Offside Front Brake pipe excessively corroded to rear (1.1.11 (c))**MOT #9**

2018-04-04 16:21

MOT test number

820412504341

Result**✓ Passed****Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #8**

2017-03-27 08:32

MOT test number

324807991339

Result**✓ Passed****Advice** Both/front/tyres/worn/inner/edges**MOT #7**

2017-03-27 08:32

MOT test number

353520876719

Result**✗ Failed****Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Advice** Both/front/tyres/worn/inner/edges**Pass with rectification** Offside Front Headlamp aim beam image obviously incorrect low/aim (1.8.A.1b)

**MOT #6** 2016-03-15 14:47**MOT test number** 171566861654**Result** ✓ Passed**Advice** O/s/r and n/s/r tyres cracking with age nail in o/s/r tyre**MOT #5** 2016-03-15 11:28**MOT test number** 179806754360**Result** ✗ Failed**Advice** O/s/r and n/s/r tyres cracking with age nail in o/s/r tyre**Fail** Nearside Rear Inner Brake pipe excessively corroded (3.6.B.2c)**MOT #4** 2015-03-25 13:59**MOT test number** 846494685033**Result** ✓ Passed**MOT #3** 2015-03-25 13:59**MOT test number** 446474385009**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2014-04-02 12:06**MOT test number** 156402594460**Result** ✓ Passed**MOT #1** 2013-04-22 12:01**MOT test number** 467422113167**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-04-23
Last registration	2021-04-09
Complete history	See info



Registration #1	2010-04-23	12 mi
Registration #2	2013-04-22	33.750 mi
Registration #3	2014-04-02	50.001 mi
Registration #4	2015-03-25	61.692 mi
Registration #5	2016-03-15	71.491 mi
Registration #6	2016-03-15	71.491 mi
Registration #7	2017-03-27	80.061 mi
Registration #8	2017-03-27	80.061 mi
Registration #9	2018-03-27	80.061 mi
Registration #10	2018-03-27	80.061 mi
Registration #11	2018-03-27	80.061 mi
Registration #12	2018-03-27	80.061 mi
Registration #13	2018-03-27	80.061 mi
Registration #14	2018-03-27	80.061 mi
Registration #15	2018-03-27	80.061 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1161 kg
Max. allowed weight	1605 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number	AL63837
---------------	---------