





General information

Make	HYUNDAI
Model	I30 T-GDI SE NAV
Colour	Red
Year of manufacture	2018
Top speed	117 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	171 Nm at 4.000 rpm
Engine capacity	998 сс
Cylinders	3
Fuel type	Petrol
Consumption city	47.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	115 g/km
CO2 label	С







Internet history

Entry 1	
Date	

2022-02-24

Listing price

Pictures

View report

14



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-03
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	10
Total items failed	5

MOT #7	2024-02-20 10:01
MOT test number	691591038457
Result	✓ Passed
Next expiry date	2025-03-03
Advice Manufactures under body covers fitted restricting inspection of component	ts
Advice Tyre worn close to legal limit/worn on edge NSF and OSF inner edges (5.2.3 (e))	
Advice Manufactures under trays fitted restricting inspection of components	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	4 (a) (ii))

МОТ #6	2024-02-20 10:01	
MOT test number	274647211086	
Result	× Failed	
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Tyre worn close to legal limit/worn on edge NSF and OSF inner edges (5.2.3 (e))		
Advice Manufactures under trays fitted restricting inspection of components		
Pass with rectification Headlamp aim too high Both (4.1.2 (a))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Manufactures under body covers fitted restricting inspection of components		





MOT #5	2023-03-01 13:33
MOT test number	506706084231
Result	✓ Passed
MOT #4	2023-03-01 11:22
MOT test number 902640618695	
Result	🗙 Failed
Fail Nearside Front Tyre has a tear, caused by separation or partial failur	re of its structure (5.2.3 (d) (ii))
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))	
Fail Nearside Rear Tyre has a tear, caused by separation or partial failure	e of its structure (5.2.3 (d) (ii))

МОТ #3	2022-02-19 09:18
MOT test number	911841173894
Result	✓ Passed
MOT #2	2021-03-04 10:10
MOT test number	849065958521
Result	✓ Passed
MOT #1	2021-03-04 10:10
MOT test number	578988372654
Result	🗙 Failed

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))



Tax & MOT check

✓	✓
Taxed	MOT
Tax due:	Expires:
1 March 2025	3 March 2025
Tax status	Valid until 1 March
Days left	306
MOT expiry date	3 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	K K K
Damage 2	AMPL
	F Store
Date	 1. F
Category	 ant
Туре	

Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-03-01
Last registration	2024-02-20
Complete history	See info



Registration #1	2018-03-01	20 mi
Registration #2	2021-03-04	22.989 mi
Registration #3	2021-03-04	22.989 mi
Registration #4	2022-02-19	29.996 mi
Registration #5		11.117 esi
Registration #6		11.117 esi
Registration #7		11.177 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

50225	Air conditioning
50295	
50482	
60501	
0566	
0567	
0569	

Safety ratings

NCAP rating	****
Adult	88%
Children	84%
Pedestrian	64%
Safety systems	68%
Overall rating	78%
Video	see crash video



Dimensions & weight	
Width	1795 mm
Height	1425 mm
Length	4455 mm
Wheel base	2650 mm
Kerb weight	1342 kg
Max. allowed weight	1800 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	G3LCJP021400