



report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 2

Date	2021-07-31
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-30
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-21
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	47
Total items failed	5

MOT #13	2023-04-26 15:24
MOT test number	230874193005
Result	✓ Passed
Next expiry date	2024-05-21



MOT #12

2022-05-21 09:39

MOT test number

707484368919

Result

✓ Passed

- Advice

Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice

Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Offside Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice

Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. BOTH SIDES (1.4.2 (a) (i))
- Advice

Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice

Nearside Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Central Rear Passenger seat(s) missing at time of test NOT UP RIGHT THE TIME OF TEST
- Advice

Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #11**

2022-05-20 16:12

MOT test number

955682418567

Result**✗ Failed**

- Advice** Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. BOTH SIDES (1.4.2 (a) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Central Rear Passenger seat(s) missing at time of test NOT UP RIGHT THE TIME OF TEST
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Fail** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Front Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

**MOT #10**

2021-05-11 09:22

MOT test number

169797765388

Result

✓ Passed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bush (5.3.4 (a) (i))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #9

2020-05-22 10:20

MOT test number

715122191551

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #8

2019-04-10 09:13

MOT test number

185093578651

Result

✓ Passed

- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #7

2018-04-16 11:48

MOT test number

892948398095

Result

✓ Passed

- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Engine Bay Covers And Under-Trays Fitted

**MOT #6** 2018-04-16 11:48**MOT test number** 878641387297**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Engine Bay Covers And Under-Trays Fitted**MOT #5** 2017-04-24 13:02**MOT test number** 912170092520**Result** ✓ Passed**Advice** Engine covers and under-tray fitted**MOT #4** 2016-04-05 08:44**MOT test number** 707917910957**Result** ✓ Passed**MOT #3** 2015-03-30 14:11**MOT test number** 437649885015**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #2** 2014-04-07 16:28**MOT test number** 135297394438**Result** ✓ Passed



MOT #1	2013-04-01 13:02
MOT test number	246471693020
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
21 May 2024

Tax status	Valid until 1 May
Days left	368
MOT expiry date	21 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-05-05
Last registration	2023-04-26
Complete history	See info



Registration #1	2010-05-05	26 mi
Registration #2	2013-04-01	21.365 mi
Registration #3	2014-04-07	29.445 mi
Registration #4	2015-03-30	37.735 mi
Registration #5	2016-04-05	47.243 mi
Registration #6	2017-04-24	57.998 mi
Registration #7	2018-04-16	69.886 mi
Registration #8	2018-04-16	69.886 mi
Registration #9	2019-05-20	75.277 mi
Registration #10	2019-05-20	75.277 mi
Registration #11	2019-05-20	75.277 mi
Registration #12	2019-05-20	75.277 mi
Registration #13	2019-05-20	75.277 mi
Registration #14	2019-05-20	75.277 mi
Registration #15	2019-05-20	75.277 mi
Registration #16	2019-05-20	75.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	AS55605