





General information

Make	PEUGEOT
Model	HORIZON BLUE HDI S/S TEPEE ALLURE
Colour	Black
Year of manufacture	2016
Top speed	101 mph
0 - 60 mph	13.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	61.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	68.9 mpg
CO2 emission	109 g/km
CO2 label	В







Internet history

Entry 3	
Date	2022-10-16
Pictures	12
Listing price	View report








source: cargurus.co.uk

Entry 2	
Date	2021-10-13
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1			
Date	2021-10-12		
Pictures	13		
Listing price	View report		



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-16
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	14
Total items failed	4

MOT #8	2024-04-17 12:55
MOT test number	958028829322
Result	✓ Passed
Next expiry date	2025-04-16
Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))	

MOT #7	2024-04-12 14:23
MOT test number	322726802578
Result	🗙 Failed
Fail Nearside Rear Position lamp not working (4.2.1 (a) (ii))	
FailRear Passenger's seat insecure All (6.2.6 (a) (ii))	
Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Coil spring corroded Both sides (5.3.1 (b) (i))	
Fail Horn not working (7.7 (a))	

МОТ #6	2022-10-20 10:37
MOT test number	701800566863
Result	✓ Passed





MOT #5	2022-04-29 06:41
MOT test number	562712079485
Result	✓ Passed
MOT #4	2021-10-05 10:14
MOT test number	569690178399
Result	Passed
MOT #3	2021-02-27 12:04
MOT test number	542126209966
Result	Passed
Advice Offside Front tyre cracked and perished but not as far as cords or ply	

Advice	Offside Rear tyre cracked and perished but not as far as cords or ply
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front tyre cracked and perished but not as far as cords or ply
Advice	Nearside Rear tyre cracked and perished but not as far as cords or ply
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #2		2020-02-10 11:03
MOT test	number	113315009432
Result		Passed
Advice	Rear Vehicle converted for wheelchair access, nearside and middle rear seat	s have been removed

but seat belts still present.





MOT #1		2019-03-01 12:27
MOT test	number	644182327054
Result		✓ Passed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice (seats not	Unable to fully check operation and condition of nearside rear and centre refitted)	ear seats and seatbelts
Advice	Front Items removed from driver's view prior to test	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Front wiper blades beginning to smear	



Tax & MOT check

	✓ Taxed		✓ MOT
Tax due: 1 April 2025		Expires: 16 April 2025	
Tax status			Valid until 1 April
Days left			337
MOT expiry date			16 April 2025
Full MOT history			See MOT history
Tax calculation			
Vehicle class		49	

venicie class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second s	

and a second	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2016-04-29
Last registration	2024-04-17
Complete history	See info



Registration #1	2016-04-29	19 mi
Registration #2	2019-03-01	10.662 mi
Registration #3	2020-02-10	14.188 mi
Registration #4	2021-02-27	16.532 mi
Registration #5	2021-10-05	18.181 mi
Registration #6		11.777 mi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.117 esi





Car features

S0225	Air conditioning
\$0295	
50482	
\$0501	
50566	
S0567	
S0569	

Safety ratings

Number of axles CarCheck.co.uk

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	<u>see crash video</u>



Dimensions & weight	
Width	2112 mm
Height	1862 mm
Length	4384 mm
Wheel base	2728 mm
Max. allowed weight	2060 kg
Additional information	
Fuel tank capacity	53
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

2

Engine number

JBHB3076096