



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	PARTNER BLUE HDI S L1
Colour	White
Year of manufacture	2016
Top speed	101 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	112 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-08-25
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-06-22
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	17
Total items failed	0

MOT #6	2023-06-15 14:15
MOT test number	668620122306
Result	✓ Passed
Next expiry date	2024-06-22

MOT #5	2023-06-14 15:50
MOT test number	782676522056
Result	✗ Failed
<b>DANGEROUS</b> Stop lamp(s) remains on when the brakes are released (4.3.2 (a) (iii))	
<b>Minor</b> Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	

MOT #4	2022-06-23 12:40
MOT test number	139449526759
Result	✓ Passed
<b>Advice</b> Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
<b>Advice</b> Offside Rear Tyre slightly damaged/cracking or perishing cracking badly (5.2.3 (d) (ii))	
<b>Minor</b> Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
<b>Advice</b> Front bolts loose on gearbox	
<b>Advice</b> Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))	
<b>Advice</b> Front Oil leak, but not excessive all over engine (8.4.1 (a) (i))	

**MOT #3**

2022-06-22 15:03

**MOT test number**

630672135645

**Result****✗ Failed****Advice**

Front Oil leak, but not excessive all over engine (8.4.1 (a) (i))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**DANGEROUS**

Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing cracking badly (5.2.3 (d) (ii))

**Minor**

Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**Advice**

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Front bolts loose on gearbox

**DANGEROUS**

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MOT #2**

2021-06-22 10:47

**MOT test number**

749912734596

**Result****✓ Passed****MOT #1**

2020-09-05 15:08

**MOT test number**

483080944824

**Result****✓ Passed****Advice**

Play in steering rack inner joint(s)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
22 June 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	247
<b>MOT expiry date</b>	22 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 275,00,-
<b>Standard rate (6 months)</b>	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YF66EGK
Plate since	2019-03-29
Current registration	YF66EGK
Plate since	2019-03-29

More info >





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-11-09
Last registration	2023-06-15
Complete history	<a href="#">See info</a>



Registration #1	2016-11-09	6 mi
Registration #2	2020-09-05	66.586 mi
Registration #3	2021-06-22	67.182 mi
Registration #4	2022-06-22	67.182 mi
Registration #5	2022-06-22	67.182 mi
Registration #6	2022-06-22	67.182 mi
Registration #7	2022-06-22	67.182 mi
Registration #8	2023-06-15	67.182 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1810 mm
Height	1828 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1314 kg
Max. allowed weight	2170 kg

Additional information

Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number	JBHB0013409