



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	EOS INDIVIDUAL TDI
Colour	Blue
Year of manufacture	2010
Top speed	128 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	50.4 mpg
CO2 emission	144 g/km
CO2 label	F





Internet history

Entry 2

Date	2021-10-08
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-10-07
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-07-26
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	36
Total items failed	13

MOT #16	2023-07-18 13:29
MOT test number	283765197590
Result	✓ Passed
Next expiry date	2024-07-26
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Minor	Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #15**

2023-07-17 13:08

MOT test number

648975913402

Result**✗ Failed**

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed excessively cracked /split/ and perished (5.2.3 (d) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Minor** Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice** Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Advice** Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #14

2022-07-27 08:04

MOT test number

889558650273

Result**✓ Passed**

- Minor** Nearside Rear Direction indicator with a multiple light source up to 1/2 not functioning (4.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

**MOT #13**

2022-06-30 13:13

MOT test number

389281017638

Result**✗ Failed**

Fail Offside Front Lower Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Advice Nearside Rear indicator LED 40% not working

Fail Offside Rear All direction indicators not working (4.4.1 (a) (ii))

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Undertrays fitted

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

MOT #12

2021-06-23 15:59

MOT test number

669609807861

Result**✓ Passed****MOT #11**

2020-07-01 13:01

MOT test number

251280298386

Result**✓ Passed****MOT #10**

2020-06-29 12:32

MOT test number

207908600406

Result**✗ Failed**

Advice Tyre pressure monitoring system warning lamp indicate fault (advice)

Fail Nearside Side repeater light intensity significantly reduced repeater lamp damaged+very dim (4.4.3 (a))

Advice Nearside rear tyre has a large nail

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (l))

**MOT #9** 2019-06-21 09:49**MOT test number** 912710296535**Result** ✓ Passed**Advice** Nearside repeater lamp has a slight damage +lens condensed**MOT #8** 2018-06-11 15:29**MOT test number** 254185419951**Result** ✓ Passed**MOT #7** 2017-06-29 13:01**MOT test number** 529493121556**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #6** 2016-06-15 12:39**MOT test number** 975164099464**Result** ✓ Passed**MOT #5** 2015-06-24 12:53**MOT test number** 368135475141**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Both rear tyres side wall perished/hasa serious cracks**Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside rear tyre outer edge

**MOT #4** 2015-06-23 12:56**MOT test number** 796274475186**Result** ✗ Failed

- Notice** Both rear tyres side wall perished/hasa serious cracks
- Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Nail in nearside rear tyre outer edge
- Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)
- Notice** Engine covers fitted obscuring some components in the engine bay

MOT #3 2014-06-28 15:31**MOT test number** 107129574129**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front tyre wearing low

MOT #2 2013-06-14 12:05**MOT test number** 136285563182**Result** ✓ Passed

- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)

MOT #1 2013-06-13 15:47**MOT test number** 228224263450**Result** ✗ Failed

- Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Front registration plate delaminated but not likely to be misread (6.3.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	BT10HVM
Plate since	2019-03-29
Current registration	BT10HVM
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-07-01
Last registration	2023-07-18
Complete history	See info



Registration #1	2010-07-01	26 mi
Registration #2	2013-06-13	28.164 mi
Registration #3	2013-06-14	28.164 mi
Registration #4	2014-06-28	37.678 mi
Registration #5	2015-06-23	44.394 mi
Registration #6	2015-06-24	44.394 mi
Registration #7	2016-06-15	52.199 mi
Registration #8	2017-06-29	56.781 mi
Registration #9	2018-06-11	61.714 mi
Registration #10	2019-06-21	68.748 mi
Registration #11	2020-06-22	75.782 mi
Registration #12	2021-06-23	82.816 mi
Registration #13	2022-06-24	89.850 mi
Registration #14	2023-06-25	96.884 mi
Registration #15	2023-06-26	96.884 mi
Registration #16	2023-06-27	96.884 mi
Registration #17	2023-06-28	96.884 mi
Registration #18	2023-06-29	96.884 mi
Registration #19	2023-06-30	96.884 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Kerb weight	1552 kg
Max. allowed weight	2000 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	CBA 700743