





General information

Make	FIAT
Model	PUNTO POP
Colour	White
Year of manufacture	2015
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption


Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	65.7 mpg
Consumption combined	53.3 mpg
CO2 emission	124 g/km
CO2 label	D






Internet history

Entry 1	
Date	2021-12-17
Pictures	29
Listing price	View report





source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-12
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	9
Total items failed	5

МОТ #8	2024-03-13 13:01
MOT test number	505716153683
Result	✓ Passed
Next expiry date	2025-03-12
Advice Front exhaust fleixble joint worn	
Advice (a) (i))Nearside Rear Suspension arm pin or bush worn but not resulting in excess	ive movement (5.3.4
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14	(a) (ii))
Minor Battery insecure but not likely to fall from carrier (4.13 (a) (i))	
Advice Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #7	2023-01-24 15:45
MOT test number	474273071706
Result	✓ Passed

MOT #6	2023-01-12 16:07
MOT test number	303874791828
Result	🗙 Failed
Fail Nearside Headlamp aim too low (4.1.2 (a))	
Fail Offside Rear Seat belt not functioning as intended (7.1.2 (c))	
Advice Brake pad wear warning light	





MOT #5		2021-12-21 08:23
MOT test	st number	266135766420
Result		✓ Passed
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1

MOT #4	2021-01-05 09:29
MOT test number	681873897535
Result	✓ Passed

MOT #3	2020-01-16 16:51
MOT test number	448070594818
Result	✓ Passed

MOT #2	2019-08-19 10:32
MOT test number	481824595709
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	

MOT #1	2019-08-16 15:24
MOT test number	899786559790
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Dumage 2	E E E E
Date	J.
Category	amer
Туре	

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



EN15UKH report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-29
Last registration	2024-03-13
Complete history	See info



Registration #1	2015-06-29	22 mi
Registration #2	2019-08-16	34.686 mi
Registration #3	2019-08-19	34.686 mi
Registration #4	2020-01-16	35.155 mi
Registration #5	2021-01-05	47.786 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1575 kg
Additional information	
Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 10/10

Number of axles	2
Engine number	1146933