



Mercedes-Benz

DS04DAL

report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 111 CDI EXTRA LONG TRAVELINER
Colour	Blue
Year of manufacture	2004
Gearbox	6 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	9999 Nm at 9.999 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-13
Pictures	19
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-07-07
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	11
Total items failed	6

MOT #12 2022-07-08 13:52

MOT test number 740795257620

Result ✓ Passed

Next expiry date 2023-07-07

- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear inner and outer sill corroded
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11 2021-07-06 17:45

MOT test number 528115195476

Result ✓ Passed

- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #10**

2021-07-05 13:08

MOT test number

994995046182

Result

✗ Failed

- Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Fail** Nearside Rear Stop lamp(s) light intensity significantly reduced (4.3.3 (a) (ii))
- Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Horn not working (7.7 (a) (ii))
- Fail** Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
- Fail** Cab or chassis has excessive corrosion, seriously affecting its strength within 30cm of a cab mounting (6.2.2 (d) (i))

MOT #9

2020-06-08 10:54

MOT test number

493776639901

Result

✓ Passed

- Advice** Rear Outer Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security Sill (6.2.2 (d) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both side (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both side (1.1.14 (a) (ii))

MOT #8

2017-03-24 21:59

MOT test number

189838116773

Result

✓ Passed

MOT #7

2015-03-09 22:32

MOT test number

538838665000

Result

✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)



MOT #6	2014-02-20 14:28
MOT test number	656591954095
Result	✓ Passed
MOT #5	2012-03-09 14:22
MOT test number	196739562044
Result	✓ Passed
MOT #4	2011-02-23 17:27
MOT test number	478514151073
Result	✓ Passed
MOT #3	2010-01-23 13:04
MOT test number	960463520072
Result	✓ Passed
MOT #2	2008-04-23 09:32
MOT test number	494544618100
Result	✓ Passed
MOT #1	2007-04-20 13:11
MOT test number	704090317166
Result	✓ Passed



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2004-04-23
Last registration	2022-07-08
Complete history	See info



Registration #1	2004-04-23	27 mi
Registration #2	2007-04-20	78.956 mi
Registration #3	2008-04-23	90.833 mi
Registration #4	2010-01-23	104.879 mi
Registration #5	2011-02-23	114.220 mi
Registration #6	2012-03-09	124.104 mi
Registration #7	2013-03-20	134.000 mi
Registration #8	2014-03-20	143.900 mi
Registration #9	2015-03-20	153.800 mi
Registration #10	2016-03-20	163.700 mi
Registration #11	2017-03-20	173.600 mi

More info >



Dimensions & weight

Width	1906 mm
Height	1872 mm
Length	5223 mm
Kerb weight	1965 kg
Max. allowed weight	2940 kg

Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	64698250083709