



General information

Make	VOLKSWAGEN
Model	PASSAT R LINE TDI
Colour	White
Year of manufacture	2010
Top speed	130 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	61.4 mpg
Consumption combined	50.4 mpg
CO2 emission	146 g/km
CO2 label	F





Internet history

Entry 1	
Date	2021-07-11
Pictures	15
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



## MOT history

MOT expiry date	2025-01-08
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	17
Total items failed	7

## MOT #14 2024-01-09 14:22

MOT test number 850903430419

Result ✓ Passed

Next expiry date 2025-01-08

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 2mm also worn on edges (5.2.3 (e))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge 2mm also worn on edge (5.2.3 (e))

## MOT #13 2022-09-15 12:48

MOT test number 270308699747

Result ✓ Passed

## MOT #12 2021-09-17 16:09

MOT test number 688546922866

Result ✓ Passed

**MOT #11**

2021-06-14 08:56

**MOT test number**

987013473307

**Result**

✗ Failed

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement  
Lateral track control arm inner bush. (5.3.4 (a) (i))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn to the legal limit of 1.6mm and devoid of tread inner shoulder at the time  
of test.**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MOT #10**

2020-06-03 10:36

**MOT test number**

197633976106

**Result**

✓ Passed

**Advice** Nearside front outer drive shaft constant velocity gaiter split/damaged around its rear securing  
clip.**Advice** Nearside front tyre worn unevenly across the breadth of tread.**MOT #9**

2019-06-11 11:45

**MOT test number**

916322617010

**Result**

✓ Passed

**Advice** Under guards fitted impeding visual inspections

**MOT #8** 2018-06-14 14:40**MOT test number** 555334552623**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Coil spring worn (5.3.1 (b) (i))**MOT #7** 2017-06-14 14:40**MOT test number** 533583723386**Result** ✓ Passed**MOT #6** 2016-05-17 14:07**MOT test number** 988326571999**Result** ✓ Passed**Advice** Engine cover and under trays fitted obscuring some items**MOT #5** 2015-06-08 17:29**MOT test number** 215479055178**Result** ✓ Passed**Notice** Diesel emission tested but no reading recorded.**MOT #4** 2014-05-21 12:30**MOT test number** 387081044113**Result** ✓ Passed**MOT #3** 2014-02-27 13:52**MOT test number** 586298454069**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #2	2014-02-27 13:52
MOT test number	598418754065
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Notice	Engine covers fitted obscuring some components in the engine bay
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2013-02-26 10:07
MOT test number	149967653446
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 May 2025

✓  
**MOT**  
**Expires:**  
8 January 2025

<b>Tax status</b>	Valid until 1 May
<b>Days left</b>	366
<b>MOT expiry date</b>	8 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>NJ10XSK</b>
Plate since	2024-03-29
Current registration	 <b>NJ10XSK</b>
Plate since	2024-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-01
Last registration	2024-01-09
Complete history	<a href="#">See info</a>



Registration #1	2010-03-01	22 mi
Registration #2	2013-02-26	59.382 mi
Registration #3	2014-02-27	76.685 mi
Registration #4	2014-05-21	78.557 mi
Registration #5	2015-06-08	82.141 mi
Registration #6	2016-05-17	86.736 mi
Registration #7	2017-06-14	95.985 mi
Registration #8	2018-06-14	104.002 mi
Registration #9	2019-06-14	112.019 mi
Registration #10	2020-06-14	120.036 mi
Registration #11	2021-06-14	128.053 mi
Registration #12	2022-06-14	136.070 mi
Registration #13	2023-06-14	144.087 mi
Registration #14	2024-01-09	150.000 mi
Registration #15	2024-01-09	150.000 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1820 mm
Height	1472 mm
Length	4765 mm
Wheel base	2709 mm
Kerb weight	1454 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4

Number of seats	5
Number of axles	2
Engine number	CBA 694229