



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SE SPORT
Colour	White
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	8.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	145 BHP
Max. torque	185 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	27.7 mpg
Consumption extra urban	50.4 mpg
Consumption combined	38.7 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)

**MOT history**

MOT #15	2021-03-29 12:42
MOT test number	782169367135
Result	✓ Passed
Next expiry date	2022-03-28

MOT #14	2021-03-29 08:04
MOT test number	759440817621
Result	✗ Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	

MOT #13	2020-12-04 10:18
MOT test number	678730042926
Result	✓ Passed

MOT #12	2019-12-07 10:28
MOT test number	778310455525
Result	✓ Passed
Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #11	2018-12-07 09:15
MOT test number	367210636046
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

**MOT #10** 2017-12-09 09:26**MOT test number** 974020343732**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2016-12-20 08:43**MOT test number** 974910614395**Result** ✓ Passed**MOT #8** 2015-12-21 15:28**MOT test number** 136587740919**Result** ✓ Passed**MOT #7** 2014-12-22 11:37**MOT test number** 187016154375**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #6** 2013-12-14 12:39**MOT test number** 476088643392**Result** ✓ Passed**MOT #5** 2013-12-14 12:39**MOT test number** 249068443363**Result** ✗ Failed**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)



MOT #4	2012-12-12 11:28
MOT test number	315797742377
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #3	2011-12-06 12:50
MOT test number	609780441348
Result	✓ Passed

MOT #2	2010-12-07 14:09
MOT test number	643931640347
Result	✓ Passed

MOT #1	2009-12-02 17:12
MOT test number	192236639348
Result	✓ Passed



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-12-28
Last registration	2021-03-29
Complete history	See info



Registration #1	2006-12-28	8 mi
Registration #2	2009-12-02	19.072 mi
Registration #3	2010-12-07	24.997 mi
Registration #4	2011-12-06	30.784 mi
Registration #5	2012-12-12	36.383 mi
Registration #6	2013-12-14	43.176 mi
Registration #7	2014-12-22	50.937 mi
Registration #8	2015-12-21	59.233 mi
Registration #9	2016-12-20	68.277 mi
Registration #10	2017-12-19	77.321 mi
Registration #11	2018-12-18	86.365 mi
Registration #12	2019-12-17	95.409 mi
Registration #13	2020-12-16	104.453 mi
Registration #14	2021-03-29	113.497 mi
Registration #15	2021-03-29	113.497 mi
Registration #16	2021-03-29	113.497 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1328 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	69500