



report date: 2024-03-28

General information

Make	KIA
Model	SOUL CRDI 2
Colour	Black
Year of manufacture	2012
Top speed	112 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-21
Pictures	30
Listing price	<a href="#">View report</a>



source: yesauto.com



## MOT history

MOT expiry date	2024-08-10
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	12
Total items failed	1

MOT #11	2023-08-08 13:41
MOT test number	398901875226
Result	✓ Passed
Next expiry date	2024-08-10
Advice	Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #10	2022-07-25 09:29
MOT test number	877665443051
Result	✓ Passed
Minor	Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #9	2021-08-11 12:35
MOT test number	792906597848
Result	✓ Passed

**MOT #8** 2021-08-09 10:56**MOT test number** 757593267245**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge 205/55/16. (5.2.3 (e))**DANGEROUS** Offside Front Tyre has ply or cords exposed 205/55/16. (5.2.3 (d) (ii))**MOT #7** 2020-05-07 10:23**MOT test number** 183451847230**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #6** 2019-05-03 15:30**MOT test number** 600238850545**Result** ✓ Passed**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2019-05-03 11:40**MOT test number** 978407631278**Result** ✗ Failed**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #4** 2018-05-08 11:10**MOT test number** 414638201812**Result** ✓ Passed



MOT #3	2018-05-08 09:36
MOT test number	281960176338
Result	✗ Failed
Fail	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #2	2017-05-06 09:00
MOT test number	641753930985
Result	✓ Passed

MOT #1	2016-05-09 08:19
MOT test number	993109702253
Result	✓ Passed



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-10-22
Last registration	2023-08-08
Complete history	<a href="#">See info</a>



Registration #1	2012-10-22	9 mi
Registration #2	2016-05-09	24.699 mi
Registration #3	2017-05-06	32.362 mi
Registration #4	2018-05-08	42.135 mi
Registration #5	2018-05-08	42.135 mi
Registration #6	2019-05-03	48.996 mi
Registration #7	2019-05-03	48.996 mi
Registration #8	2019-05-03	48.996 mi
Registration #9	2019-05-03	48.996 mi
Registration #10	2019-05-03	48.996 mi
Registration #11	2019-05-03	48.996 mi
Registration #12	2019-05-03	48.996 mi
Registration #13	2019-05-03	48.996 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4120 mm
Wheel base	2550 mm
Kerb weight	1444 kg
Max. allowed weight	1790 kg

Additional information

Fuel tank capacity	48 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FBCH542301