



YEIONNE


General information

report date: 2024-03-28

Make	SSANGYONG
Model	KORANDO ELX
Colour	Silver
Year of manufacture	2018
Top speed	115 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	176 BHP
Max. torque	400 Nm at 2.800 rpm
Engine capacity	2.157 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	152 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-16
Pictures	8
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-05-24
MOT pass rate	50 %
MOT passed	3
Failed MOT tests	3
Total advice items	2
Total items failed	6

MOT #6	2023-05-22 07:40
MOT test number	205460457135
Result	✓ Passed
Next expiry date	2024-05-24

MOT #5	2023-05-19 10:12
MOT test number	915421646547

Result	✗ Failed
--------	----------

- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure inner sidewall (5.2.3 (d) (ii))
- Fail** Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

MOT #4	2022-05-18 09:21
MOT test number	969524267215

Result	✓ Passed
--------	----------



MOT #3	2022-05-18 09:21
---------------	------------------

MOT test number	309539939736
------------------------	--------------

Result	✗ Failed
---------------	----------

Pass with rectification	Nearside Rear Tyre not fitted in accordance with side wall instructions (5.2.3 (i))
--------------------------------	---

MOT #2	2021-05-25 15:23
---------------	------------------

MOT test number	981654915745
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #1	2021-05-22 08:44
---------------	------------------

MOT test number	807257217285
------------------------	--------------

Result	✗ Failed
---------------	----------

Fail	Nearside Front Outer Brake pad(s) contaminated Cracked in half (1.1.13 (b))
-------------	---



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
24 May 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	24 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
First licence fee (12 months)	£ 645,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 1.040,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this SSANGYONG. See if, where and when this SSANGYONG had damage and the car repair costs. We also check if this SSANGYONG was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SSANGYONG salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SSANGYONG in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this SSANGYONG? How many owners did this SSANGYONG have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

SSANGYONG	SSANGYONG
SSANGYONG	SSANGYONG
SSANGYONG	SSANGYONG
SSANGYONG	SSANGYONG
SSANGYONG	SSANGYONG
SSANGYONG	SSANGYONG

More info >

Plate changes

See in this check if this SSANGYONG had different number plates.

Number of plates	1
Current registration	 YE10NNE
Plate since	2024-03-28
Current registration	 YE10NNE
Plate since	2024-03-28

More info >



Finance check

Check if this SSANGYONG is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SSANGYONG has been settled.

If not, and you buy this SSANGYONG then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SSANGYONG is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-26
Last registration	2023-05-22
Complete history	See info



Registration #1	2018-09-26	22 mi
Registration #2	2021-05-22	13.009 mi
Registration #3	2021-05-25	13.010 mi
Registration #4	2023-05-22	22.000 mi
Registration #5	2023-05-22	22.000 mi
Registration #6	2023-05-22	22.000 mi
Registration #7	2023-05-22	22.000 mi
Registration #8	2023-05-22	22.000 mi

More info >



Dimensions & weight

Width	1830 mm
Height	1710 mm
Length	4410 mm
Wheel base	2650 mm
Kerb weight	1828 kg
Max. allowed weight	2300 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	67295000505019