



report date: 2024-03-28

General information

Make	VOLVO
Model	XC70 D5 SE AWD
Colour	Blue
Year of manufacture	2009
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	205 BHP
Max. torque	420 Nm at 1.500 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	28.0 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.7 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-10-13
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-09
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	5
Total items failed	7

MOT #18	2023-05-12 11:02
MOT test number	343502570320
Result	✓ Passed
Next expiry date	2024-06-09
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #17	2022-05-10 11:20
MOT test number	144624779176
Result	✓ Passed
Advice	Nearside Rear Brake disc worn, but not excessively and o/s/r (1.1.14 (a) (i))

MOT #16	2022-05-10 09:03
MOT test number	867305628353
Result	✗ Failed
Advice	Nearside Rear Brake disc worn, but not excessively and o/s/r (1.1.14 (a) (i))
Fail	Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))

MOT #15	2021-06-10 13:51
MOT test number	200345735591
Result	✓ Passed

**MOT #14** 2021-06-01 09:43**MOT test number** 626491722001**Result** ✗ Failed**Advice** Front Lower Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**MOT #13** 2020-06-03 14:47**MOT test number** 388890369943**Result** ✓ Passed**MOT #12** 2019-05-14 09:15**MOT test number** 753243993744**Result** ✓ Passed**MOT #11** 2018-05-15 11:48**MOT test number** 120725033740**Result** ✓ Passed**MOT #10** 2017-05-16 09:24**MOT test number** 257608596927**Result** ✓ Passed**MOT #9** 2017-05-16 09:24**MOT test number** 797509549586**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #8** 2016-05-11 10:45**MOT test number** 598964424803**Result** ✓ Passed

**MOT #7** 2016-05-10 14:51**MOT test number** 794580736285**Result** ✗ Failed**Fail** Offside Rear Parking brake operation grabbing severely (3.7.C.3b)**Fail** Nearside Rear Parking brake operation grabbing severely (3.7.C.3b)**MOT #6** 2015-05-12 10:03**MOT test number** 565602035174**Result** ✓ Passed**MOT #5** 2014-05-20 12:01**MOT test number** 307270144132**Result** ✓ Passed**MOT #4** 2014-05-20 12:01**MOT test number** 616370244184**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #3** 2013-05-21 13:38**MOT test number** 988241443199**Result** ✓ Passed**MOT #2** 2013-05-21 13:38**MOT test number** 235451243409**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)



MOT #1	2012-05-29 15:45
MOT test number	978310552189
Result	✓ Passed
<div>Notice</div> Removed air freshener from interior mirror	



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 June 2024

Tax status	Valid until 1 October
Days left	156
MOT expiry date	9 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-24
Last registration	2023-05-12
Complete history	See info



Registration #1	2009-06-24	11 mi
Registration #2	2012-05-29	22.297 mi
Registration #3	2013-05-21	28.892 mi
Registration #4	2014-05-20	35.990 mi
Registration #5	2015-05-12	42.029 mi
Registration #6	2016-05-10	50.069 mi
Registration #7	2016-05-11	50.075 mi
Registration #8	2017-05-16	56.839 mi
Registration #9	2017-05-16	56.839 mi
Registration #10	2018-05-20	59.377 mi
Registration #11	2018-05-20	59.377 mi
Registration #12	2019-05-20	59.377 mi
Registration #13	2019-05-20	59.377 mi
Registration #14	2019-05-20	59.377 mi
Registration #15	2019-05-20	59.377 mi
Registration #16	2019-05-20	59.377 mi
Registration #17	2019-05-20	59.377 mi
Registration #18	2019-05-20	59.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1891 mm
Height	1713 mm
Length	4627 mm
Wheel base	2774 mm
Kerb weight	1863 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	745321