



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Grey
Year of manufacture	2010
Top speed	129 mph
0 - 60 mph	10.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	160 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	179 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-08-28
Pictures	52
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-09-14
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	35
Total items failed	4

MOT #15	2023-09-01 09:20
MOT test number	754358940881
Result	✓ Passed
Next expiry date	2024-09-14

MOT #14	2023-09-01 09:20
MOT test number	215760731390
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on dipped beam H7 bulb (4.1.1 (a) (ii))

MOT #13	2022-09-08 15:53
MOT test number	248594226877
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Shock absorbers has a reduced damping effect Both front and rear damping effect reduced (5.3.2 (d))

**MOT #12**

2022-08-27 09:17

MOT test number

693173617863

Result**✗ Failed****MAJOR** Nearside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**DANGEROUS** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MAJOR** Offside Front Suspension arm pin or bush excessively worn Lower arm bush (5.3.4 (a) (i))**MAJOR** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Shock absorbers has a reduced damping effect Both front and rear damping effect reduced (5.3.2 (d))**MOT #11**

2021-09-15 12:59

MOT test number

544091055728

Result**✓ Passed****Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**MOT #10**

2021-02-11 15:01

MOT test number

276703732531

Result

✓ Passed

Advice Hydraulic leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #9**

2020-01-08 15:12

MOT test number

169382624926

Result

✓ Passed

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Oil leak**Advice** Items removed from driver's view prior to test**Advice** Under trays fitted, obscuring underside components**Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Both rear tyres inner edges devoid of tread**MOT #8**

2019-01-31 11:26

MOT test number

803156487233

Result

✓ Passed

Advice Front Both front outer c/v boots wet with grease**MOT #7**

2018-01-29 15:32

MOT test number

977059979549

Result

✓ Passed

Advice Nearside Front Outer C/v boot leaking grease.**Advice** C/v boot leaking grease.

**MOT #6** 2017-01-18 14:25**MOT test number** 774247268739**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front O/s front tyre at 2.5mm**Advice** Nearside Rear N/s rear tyre at 2.5mm**MOT #5** 2017-01-18 10:01**MOT test number** 888466756091**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Advice** Offside Front O/s front tyre at 2.5mm**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Fail** Electronic parking brake warning indicates a malfunction (3.1.7)**Advice** Nearside Rear N/s rear tyre at 2.5mm**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #4** 2016-01-19 12:42**MOT test number** 474141652129**Result** ✓ Passed**MOT #3** 2015-01-19 14:27**MOT test number** 156739515079**Result** ✓ Passed**MOT #2** 2014-01-21 12:58**MOT test number** 185471924410**Result** ✓ Passed



MOT #1	2013-01-17 10:56
MOT test number	935127713073
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Plastic sill covers fitted



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
14 September 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	14 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-01-31
Last registration	2023-09-01
Complete history	See info



Registration #1	2010-01-31	18 mi
Registration #2	2013-01-17	40.711 mi
Registration #3	2014-01-21	52.500 mi
Registration #4	2015-01-19	66.078 mi
Registration #5	2016-01-19	77.841 mi
Registration #6	2017-01-18	85.958 mi
Registration #7	2017-01-18	85.958 mi
Registration #8	2018-01-29	90.911 mi
Registration #9	2019-01-31	94.929 mi
Registration #10	2020-01-31	95.377 mi
Registration #11	2020-01-31	95.377 mi
Registration #12	2020-01-31	95.377 mi
Registration #13	2020-01-31	95.377 mi
Registration #14	2020-01-31	95.377 mi
Registration #15	2020-01-31	95.377 mi
Registration #16	2020-01-31	95.377 mi
Registration #17	2020-01-31	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	81%
Children	77%
Pedestrian	32%
Safety systems	83%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1860 mm
Height	1479 mm
Length	4289 mm
Wheel base	2815 mm
Kerb weight	1595 kg
Max. allowed weight	2286 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYWT4004886