





report date: 2024-03-28

General information

Make	KIA
Model	SOUL TEMPEST
Colour	Cream
Year of manufacture	2010
Top speed	110 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	124 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	43.5 mpg
CO2 emission	156 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

		1
ᆮ	HLIV	-

Date	2021-08-12
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

N/I	α		ıc	-	r\/
101	•		115		ıv
	•	Γh			. ,

MOT expiry date	2025-03-10
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	17
Total items failed	12

MOT #16	2024-03-11 15:29
MOT test number	872639643990
Result	✓ Passed
Next expiry date	2025-03-10
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #	15	2024-01-30 16:11
MOT te	st number	873139168293
Result		X Failed
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Fail	Exhaust silencer likely to become detached (8.1.1 (b) (ii))	
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its struc	ture (5.2.3 (d) (ii))
Fail	Fail Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advic	e Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its struc	cture (5.2.3 (d) (ii))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #14

MOT test number

524002849435

Result

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13 2022-11-29 14:01 **MOT** test number 599510107214 Result × Failed Fail Nearside Track rod end ball joint worn to the extent there is a serious risk of detachment (2.1.3 (b) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i)) Fail Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice**

MOT #12

MOT test number

Result

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT test number

958148130702

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Electronic power steering warning lamp indicates a system malfunction (2.6 (a))

MOT #10

MOT test number

Result

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #9

MOT test number

Result

Advice Child Seat fitted not allowing full inspection of adult belt

MOT test number

Result

Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #7

MOT test number

Result

Advice

Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #6	2017-09-29 13:45
MOT test number	998384845363
Result	✓ Passed
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #5	2016-09-28 10:18
MOT test number	466501439163
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #4		2015-09-30 10:07
MOT test number		712124940767
Result		✓ Passed
MOT #3		2014-09-27 10:36
MOT test number		498080474204
Result		X Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	

MOT #2	2014-09-27 10:36
MOT test number	928790674246
Result	✓ Passed
MOT #1	2013-09-26 15:10
MOT test number	319319063298
Result	✓ Passed

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

OWITE HISTORY	Owner	history
---------------	-------	---------

Owner mistory	
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-09-30
Last registration	2024-03-11
Complete history	See info



Registration #1	2010-09-30	18 mi
Registration #2	2013-09-26	25.009 mi
Registration #3	2014-09-27	33.634 mi
Registration #4	2015-09-30	39.879 mi
Registration #5	2016-09-28	44.918 mi
Registration #6	2017-09-29	50.226 mi
Registration #7	2018-09-27	54.582 mi
Registration #8	2019-10-01	59.327 mi
Registration #9	2019-10-02	59.327 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		D.277 es

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1785 mm
Height	1610 mm
Length	4105 mm
Wheel base	2550 mm
Kerb weight	1245 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	48 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles 2

Engine number G4FCAH482176