



PEUGEOT



BG53ZKT

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 HDI LX
Colour	Red
Year of manufacture	-
Top speed	104 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	150 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	65.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-12
Pictures	0
Listing price	<a href="#">View report</a>

source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #25</b>	2020-08-14 12:27
<b>MOT test number</b>	668474820298
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-08-13

<b>MOT #24</b>	2020-08-10 13:35
<b>MOT test number</b>	505846350907
<b>Result</b>	✗ Failed
<b>Fail</b> Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
<b>Fail</b> Nearside Headlamp aim not tested (4.1.2 (b))	
<b>Minor</b> Indicator switch faulty (4.4.2 (a) (i))	

<b>MOT #23</b>	2019-08-13 10:59
<b>MOT test number</b>	967941224581
<b>Result</b>	✓ Passed

<b>MOT #22</b>	2018-08-09 11:43
<b>MOT test number</b>	334974651004
<b>Result</b>	✓ Passed

<b>MOT #21</b>	2018-08-09 11:07
<b>MOT test number</b>	999200100635
<b>Result</b>	✗ Failed
<b>Pass with rectification</b> Offside Side repeater incorrect colour (4.4.3 (a))	
<b>Pass with rectification</b> Nearside Headlamp aim too low (4.1.2 (a))	
<b>Fail</b> Nearside Front Direction indicator incorrect colour (4.4.3 (a))	
<b>Pass with rectification</b> Offside Headlamp aim too high (4.1.2 (a))	

**MOT #20** 2017-08-14 10:35**MOT test number** 572966355068**Result** ✓ Passed**MOT #19** 2017-08-11 10:29**MOT test number** 295349631266**Result** ✗ Failed**Fail** Fuel tank insecure (7.2.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)**MOT #18** 2016-08-03 11:35**MOT test number** 587658648557**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #17** 2016-08-03 11:35**MOT test number** 471889623758**Result** ✗ Failed**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #16** 2015-07-24 10:46**MOT test number** 555545605295**Result** ✓ Passed

**MOT #15** 2015-07-24 10:46**MOT test number** 679635605267**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too high (1.8)**Pass with rectification** Offside Headlamp aim too high (1.8)**MOT #14** 2014-08-12 14:30**MOT test number** 735534924253**Result** ✓ Passed**MOT #13** 2013-08-02 13:44**MOT test number** 289564213224**Result** ✓ Passed**MOT #12** 2013-08-02 13:44**MOT test number** 638144913247**Result** ✗ Failed**Pass with rectification** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)**MOT #11** 2012-08-14 12:56**MOT test number** 367657022228**Result** ✓ Passed**MOT #10** 2011-08-05 11:55**MOT test number** 315027211437**Result** ✓ Passed

**MOT #9** 2011-08-05 11:55**MOT test number** 729197411256**Result** ✗ Failed**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2010-09-24 11:41**MOT test number** 831847860270**Result** ✓ Passed**MOT #7** 2010-09-08 14:52**MOT test number** 600401150278**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #6** 2009-09-11 09:50**MOT test number** 642654059247**Result** ✓ Passed**MOT #5** 2009-09-09 15:46**MOT test number** 241792659289**Result** ✗ Failed**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Emissions not tested (7.0)**MOT #4** 2008-09-09 13:47**MOT test number** 943233958275**Result** ✓ Passed



MOT #3	2007-10-03 13:36
MOT test number	662776877219
Result	✓ Passed

MOT #2	2007-10-03 11:57
MOT test number	304536977433
Result	✗ Failed
Fail	Rear Exhaust system not adequately supported (7.1.1)

MOT #1	2006-10-06 11:25
MOT test number	434649376219
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-11-07
Last registration	2020-08-14
Complete history	<a href="#">See info</a>



Registration #1	2003-11-07	16 mi
Registration #2	2006-10-06	29.967 mi
Registration #3	2007-10-03	41.583 mi
Registration #4	2007-10-03	41.589 mi
Registration #5	2008-09-09	53.658 mi
Registration #6	2009-09-09	63.013 mi
Registration #7	2009-09-11	63.023 mi
Registration #8	2010-09-08	73.695 mi
Registration #9	2010-09-24	74.237 mi
Registration #10	2011-08-05	83.321 mi
Registration #11	2012-08-14	93.123 mi
Registration #12	2013-08-02	102.576 mi
Registration #13	2014-08-02	112.028 mi
Registration #14	2015-08-02	121.480 mi
Registration #15	2016-08-02	130.932 mi
Registration #16	2017-08-02	140.384 mi
Registration #17	2018-08-02	149.836 mi
Registration #18	2019-08-02	159.288 mi
Registration #19	2020-08-14	168.740 mi
Registration #20	2021-08-14	178.192 mi
Registration #21	2022-08-14	187.644 mi
Registration #22	2023-08-14	197.096 mi
Registration #23	2024-03-28	206.548 mi
Registration #24	2024-03-28	216.000 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1083 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Engine number	FD320450807