



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	BEETLE DESIGN TDI BLUEMOTION TECHNOLOGY DSG
Colour	White
Year of manufacture	2015
Top speed	123 mph
Gearbox	6 speed Semi Auto

Engine & fuel consumption

Power	148 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	61.4 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-10-02
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-12-20
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #8	2022-12-21 11:39
MOT test number	873980908109
Result	✓ Passed
Next expiry date	2023-12-20

MOT #7	2022-01-25 14:25
MOT test number	273677041843
Result	✓ Passed

MOT #6	2021-07-02 13:25
MOT test number	879622734785
Result	✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge bold (5.2.3 (e))

Advice Emissions too clean to register on DSM

MOT #5	2021-07-02 13:25
MOT test number	687963702853
Result	✗ Failed

Advice Emissions too clean to register on DSM

Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge inner edge bold (5.2.3 (e))

**MOT #4** 2020-07-10 15:16**MOT test number** 290932880193**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Emissions too clean for DSM**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #3** 2020-07-10 08:21**MOT test number** 326596952568**Result** ✗ Failed**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Emissions too clean for DSM**MOT #2** 2019-06-27 08:26**MOT test number** 960982602684**Result** ✓ Passed**MOT #1** 2018-07-09 11:23**MOT test number** 733384373326**Result** ✓ Passed**Advice** Emissions too clean to register on DSM



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✗
MOT

Expired:
20 December 2023

Tax status	Valid until 1 June
Days left	33
MOT expiry date	20 December 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-05-01
Last registration	2022-12-21
Complete history	See info



Registration #1	2015-05-01	20 mi
Registration #2	2018-07-09	16.202 mi
Registration #3	2019-06-27	20.197 mi
Registration #4	2020-07-10	23.075 mi
Registration #5	2020-07-10	23.075 mi
Registration #6	2020-07-10	23.075 mi
Registration #7	2020-07-10	23.075 mi
Registration #8	2020-07-10	23.075 mi
Registration #9	2020-07-10	23.075 mi
Registration #10	2020-07-10	23.075 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	2021 mm
Height	1473 mm
Length	4278 mm
Wheel base	2540 mm
Kerb weight	1529 kg
Max. allowed weight	1910 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles

2

Engine number

CUUB018610