



report date: 2024-03-29

General information

Make	AUDI
Model	A4 T QU S LINE SPECIAL ED
Colour	Grey
Year of manufacture	2006
Top speed	148 mph
0 - 60 mph	7.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	220 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.0 mpg
CO2 emission	214 g/km
CO2 label	K





MOT history

MOT expiry date	2021-02-10
MOT pass rate	55 %
MOT passed	11
Failed MOT tests	9
Total advice items	25
Total items failed	26

MOT #20	2020-02-11 16:59
MOT test number	151394615423
Result	✓ Passed
Next expiry date	2021-02-10
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2020-02-08 10:10
MOT test number	850830185417
Result	✗ Failed
Fail	Offside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #18	2019-02-11 10:23
MOT test number	197366482334
Result	✓ Passed
Advice	Offside Front Nail in tyre
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #17**

2019-02-09 10:20

MOT test number

369407329621

Result

✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Rear Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Nail in tyre**MOT #16**

2018-11-26 12:46

MOT test number

572436105489

Result

✗ Failed

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Rear Tyre worn close to legal limit/worn on edge Both sides on limit (5.2.3 (e))**Fail** Nearside Rear Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Fail** Front Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15**

2017-11-27 17:01

MOT test number

610679768161

Result

✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Brake pad warning light illuminated

**MOT #14** 2017-11-27 13:39**MOT test number** 339906591665**Result** ✗ Failed**Fail** Central Front Exhaust has a major leak of exhaust gases at pipe joint (7.1.2)**Fail** Emissions not tested exhaust blow (7.3.A.1)**Fail** Central Front Exhaust has a major leak of exhaust gases at pipe joint (7.1.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Brake pad warning light illuminated**MOT #13** 2016-11-07 16:10**MOT test number** 929208076072**Result** ✓ Passed**MOT #12** 2016-10-24 12:07**MOT test number** 656033538179**Result** ✗ Failed**Fail** Front Lower Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt Both sides (2.4.G.2)**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)**Fail** Offside Headlamp aim too high (1.8)**Fail** Nearside Front Upper Suspension arm ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Front Tyre not fitted in accordance with side wall instructions Both sides (4.1.D.1f)**Fail** Nearside Headlamp aim too high (1.8)**Fail** Headlamp insecure Both sides (1.7.3)**MOT #11** 2015-10-14 10:08**MOT test number** 556398886222**Result** ✓ Passed

**MOT #10** 2015-10-13 13:02**MOT test number** 861562481609**Result** ✗ Failed**Fail** Nearside Front Shock absorber insecure (2.7.2b)**Fail** Offside Front Upper Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**MOT #9** 2014-10-30 12:45**MOT test number** 999203504364**Result** ✓ Passed**Notice** N/s/f tyre cut but not exposing cords**Advice** Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** O/s/r tyre cut but not exposing cords**Advice** Nearside Front Upper Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #8** 2013-11-08 14:30**MOT test number** 478952013359**Result** ✓ Passed**MOT #7** 2012-09-25 16:01**MOT test number** 359679362477**Result** ✓ Passed

**MOT #6** 2012-09-24 11:04**MOT test number** 358028162445**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2011-10-21 14:11**MOT test number** 535504191210**Result** ✓ Passed**Notice** Both front tyres low tread (dunlop 235 40 18 y) n/s/f on limit and scrubbing edges**MOT #4** 2011-10-21 10:07**MOT test number** 308744291475**Result** ✗ Failed**Notice** Both front tyres low tread (dunlop 235 40 18 y) n/s/f on limit and scrubbing edges**Fail** Exhaust system not adequately supported (7.1.1)**MOT #3** 2010-09-30 15:47**MOT test number** 314723570442**Result** ✓ Passed



MOT #2	2009-09-10 15:19
MOT test number	882193059252
Result	✓ Passed
Notice	Vehicle has undertrays fitted not allowing full inspection of the underside
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Both front upper suspension arm rubber bushes slightly torn

MOT #1	2009-09-10 14:32
MOT test number	430883959227
Result	✗ Failed
Notice	Child seat fitted not allowing full inspection of adult belt
Notice	Both front upper suspension arm rubber bushes slightly torn
Fail	Front Tyre not fitted in accordance with side wall instructions (4.1.D.1f)
Notice	Vehicle has undertrays fitted not allowing full inspection of the underside



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	YK56MCD
Plate since	2019-09-29
Current registration	YK56MCD
Plate since	2019-09-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-09-01
Last registration	2020-02-11
Complete history	See info



Registration #1	2006-09-01	27 mi
Registration #2	2009-09-10	63.891 mi
Registration #3	2009-09-10	63.891 mi
Registration #4	2010-09-30	69.362 mi
Registration #5	2011-10-21	76.027 mi
Registration #6	2011-10-21	76.027 mi
Registration #7	2012-09-24	80.444 mi
Registration #8	2012-09-25	80.453 mi
Registration #9	2013-11-08	85.986 mi
Registration #10	2014-10-30	90.976 mi
Registration #11	2015-10-13	94.187 mi
Registration #12	2016-02-20	95.277 mi
Registration #13	2016-02-20	95.277 mi
Registration #14	2016-02-20	95.277 mi
Registration #15	2016-02-20	95.277 mi
Registration #16	2016-02-20	95.277 mi
Registration #17	2016-02-20	95.277 mi
Registration #18	2016-02-20	95.277 mi
Registration #19	2016-02-20	95.277 mi
Registration #20	2016-02-20	95.277 mi
Registration #21	2016-02-20	95.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1772 mm
Height	1453 mm
Length	4586 mm
Wheel base	2808 mm
Kerb weight	1585 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BUL 003867