




report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI S 5STR
Colour	Grey
Year of manufacture	2005
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-08
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2022-07-20
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	55
Total items failed	9

MOT #19 2021-07-21 16:00

MOT test number 103960587263

Result ✓ Passed

Next expiry date 2022-07-20

Minor Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

MOT #18 2020-07-07 08:58

MOT test number 325774213110

Result ✓ Passed

MOT #17 2019-06-20 09:04

MOT test number 453569373939

Result ✓ Passed

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))



MOT #16	2018-06-29 14:10
---------	------------------

MOT test number	300116785782
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #15	2018-06-29 13:26
---------	------------------

MOT test number	230577073253
-----------------	--------------

Result	✗ Failed
--------	----------

Fail	Brake servo inoperative (1.1.10 (a) (ii))
-------------	---

MOT #14	2017-07-13 10:34
---------	------------------

MOT test number	282799059786
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #13	2016-06-08 10:00
---------	------------------

MOT test number	387213437576
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #12	2015-07-02 13:59
---------	------------------

MOT test number	206143885188
-----------------	--------------

Result	✓ Passed
--------	----------

Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	---

Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
---------------	--

**MOT #11** 2014-06-18 12:26**MOT test number** 275039064165**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components

MOT #10 2013-06-13 10:24**MOT test number** 425034463137**Result** ✓ Passed

- Notice** Nearside rear brake disc backplate badly corroded
- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Notice** Items removed from driver's view prior to test

MOT #9 2012-06-23 10:09**MOT test number** 215605272459**Result** ✓ Passed

- Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #8** 2012-06-21 10:34**MOT test number** 577893572120**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear registration plate faded (6.3.1d)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear registration plate deteriorated (6.3.1d)**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Fail** Nearside Front Track rod end ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.2.C.1c)**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #7** 2011-06-22 15:07**MOT test number** 608813771100**Result** ✓ Passed**Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)**Advice** Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)**Notice** Nearside rear brake disc weather plate corroded**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**Notice** Nearside door mirror glass damaged



MOT #6	2011-06-22 09:08
MOT test number	365843971178
Result	✗ Failed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)
Advice	Rear Anti-roll bar corroded but not seriously weakened (2.4.G.1)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Nearside rear brake disc weather plate corroded
Advice	Rear registration plate deteriorated but not likely to be misread (6.3.1d)
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Notice	Nearside door mirror glass damaged

MOT #5	2010-06-16 10:45
MOT test number	931357060127
Result	✓ Passed
Notice	Front wipers smearing
Advice	Offside Rear coil spring corroded (2.4.C.1b)
Notice	Rear number plate deteriorated
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #4** 2010-06-16 09:16**MOT test number** 231697460417**Result** ✗ Failed**Advice** Offside Rear coil spring corroded (2.4.C.1b)**Notice** Front wipers smearing**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Rear number plate deteriorated**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**MOT #3** 2009-06-18 14:16**MOT test number** 704069169101**Result** ✓ Passed**Notice** Front and rear number plates deteriorated**MOT #2** 2009-06-18 14:16**MOT test number** 434899569173**Result** ✗ Failed**Pass with rectification** Nearside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)**Notice** Front and rear number plates deteriorated**Pass with rectification** Nearside Headlamp aim too low and too far to the left. (1.8)



MOT #12008-06-26 14:55

MOT test number154028578127

Result		✓ Passed
Notice	Rear number plate deteriorated	
Advice	Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Notice	Nail in nearside rear tyre	
Advice	Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

✕
Untaxed

Tax expired:
29 July 2022

✕
MOT

Expired:
20 July 2022

Tax status	Expired at 29 July 2022
Days left	639 days too late
MOT expiry date	20 July 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BL05GXV
Plate since	2019-09-29
Current registration	 BL05GXV
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2005-06-29
Last registration	2021-07-21
Complete history	See info



Registration #1	2005-06-29	22 mi
Registration #2	2008-06-26	15.471 mi
Registration #3	2009-06-18	18.869 mi
Registration #4	2010-06-16	23.087 mi
Registration #5	2010-06-16	23.087 mi
Registration #6	2011-06-22	27.451 mi
Registration #7	2011-06-22	27.451 mi
Registration #8	2012-06-21	30.798 mi
Registration #9	2012-06-23	30.800 mi
Registration #10	2013-06-13	32.811 mi
Registration #11	2013-06-20	35.277 mi
Registration #12	2013-06-20	35.277 mi
Registration #13	2013-06-20	35.277 mi
Registration #14	2013-06-20	35.277 mi
Registration #15	2013-06-20	35.277 mi
Registration #16	2013-06-20	35.277 mi
Registration #17	2013-06-20	35.277 mi
Registration #18	2013-06-20	35.277 mi
Registration #19	2013-06-20	35.277 mi
Registration #20	2013-06-20	35.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BKC 732958