





General information

Make	ΤΟΥΟΤΑ
Model	VERSO VALVEMATIC TR
Colour	Grey
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	11.1 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	145 BHP
Max. torque	180 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	47.9 mpg
Consumption combined	40.4 mpg
CO2 emission	164 g/km
CO2 label	G







Internet history

Entry 3	
Date	
Pictures	

2022-04-03

11

Listing price

View report



source: yesauto.com

Entry 2	
Date	2022-03-20
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1	
Date	2021-09-27
Pictures	29
Listing price	View report









source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-17
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	26
Total items failed	9

MOT #13		2023-05-16 09:10
MOT test	number	237313715914
Result		✓ Passed
Next expi	ry date	2024-05-17
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	

MOT #122022-05-18 12:13MOT test number817761804134ResultPassedAdviceRear Brake pad(s) wearing thin (1.1.13 (a) (ii))AdviceRear Registration plate deteriorated but not likely to be misread (0.1 (b))AdviceRear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))





MOT #11	2022-05-18 12:13	
MOT test number	473582169441	
Result	× Failed	
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))		
Pass with rectification	Electronic stability control warning lamp indicates a fault (7.12 (e))	
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		
Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))		
Pass with rectification	Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #10	2021-10-13 16:05
MOT test number	652196265505
Result	✓ Passed
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Minor Front Windscreen wiper blade defective (3.4 (b) (i))	

MOT #9		2020-08-17 15:43
MOT test	number	416785230756
Result		✓ Passed
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice	Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Registration plate deteriorated but not likely to be misread $(0.1 (b))$	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (2	1.1.14 (a) (ii))





IOT #8 2020-08-17 09:0		
IOT test number 59131500771		
esult × Faile		
Fail Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))		
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Pass with rectification Nearside Front Headlamp aim too low and too far to the right. (4.1.2 (a))		
Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Advice Front Registration plate deteriorated but not likely to be misread (0.1 (b))		
Fail Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))		
Fail Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))		
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Pass with rectification Offside Front Headlamp aim too low and too far to the right. (4.1.2 (a))		
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))		

MOT #7		2019-08-21 14:32
MOT test	number	431089146929
Result		✓ Passed
Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice	Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	

МОТ #6	2018-06-19 14:58
MOT test number	831791782879
Result	✓ Passed





MOT #5	2017-06-22 10:18
MOT test number	134759550997
Result	✓ Passed
MOT #4	2016-06-14 12:11
MOT test number	241234488626
Result	✓ Passed
MOT #3	2015-06-08 10:13
MOT test number	117319855145
Result	✓ Passed
MOT #2	2014-06-13 12:51
MOT test number	439084764144
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2013-05-30 12:44
MOT test number	357610253110
Result	✓ Passed



Tax & MOT check

Tax due: 1 June 2024	✓ Taxed	Expires: 17 May 2024	✓ МОТ
Tax status			Valid until 1 June
Days left			34
MOT expiry date			17 May 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 4. ARAPE
Туре	
Damage 2	AMPL
	E Stand
Date	 1 Alexandre
Category	 amer
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 11.111
Average private trade value	4 10 200





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plata since	





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



LV10UET report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-05-31
Last registration	2023-05-16
Complete history	See info



Registration #1	2010-05-31	11 mi
Registration #2	2013-05-30	16.641 mi
Registration #3	2014-06-13	27.476 mi
Registration #4	2015-06-08	35.494 mi
Registration #5	2016-06-14	40.206 mi
Registration #6	2017-06-22	48.253 mi
Registration #7	2018-06-19	72.034 mi
Registration #8	2019-08-21	102.774 mi
Registration #9	2020-08-17	123.037 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight	
Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1525 kg
Max. allowed weight	2125 kg
Additional information	
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles CarCheck.co.uk	2 page 13/13