





report date: 2024-03-28

## General information

| Make                | CITROEN                         |
|---------------------|---------------------------------|
| Model               | C4 GRAND BLUEHDI EXCLUSIVE PLUS |
| Colour              | Silver                          |
| Year of manufacture | 2015                            |
| Top speed           | 130 mph                         |
| 0 - 60 mph          | 9.8 seconds                     |
| Gearbox             | 6 speed Manual                  |

## Engine & fuel consumption

| Power                   | 148 BHP             |
|-------------------------|---------------------|
| Max. torque             | 370 Nm at 2.000 rpm |
| Engine capacity         | 1.997 сс            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 54.3 mpg            |
| Consumption extra urban | 74.3 mpg            |
| Consumption combined    | 65.7 mpg            |
| CO2 emission            | 105 g/km            |
| CO2 label               | В                   |



CarCheck.co.uk page 1/11



# Internet history

## Entry 1

Date 2021-01-29

Pictures 6

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date    | 2023-08-16 |
|--------------------|------------|
| MOT pass rate      | 78 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 2          |
| Total advice items | 1          |
| Total items failed | 5          |

| MOT #  | 9  | 2024-04-04 13:09 |
|--------|--|------------------|
| MOT te | st number  | 175491133028     |
| Result |  | 🗙 Failed         |
| Fail   | Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (i | i))              |
| Fail   | Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))                      |                  |
| Fail   | Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b)   | (ii))            |
| Fail   | Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))            |                  |

| MOT #8          | 2022-08-12 14:39 |
|-----------------|------------------|
| MOT test number | 598219333757     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #7          | 2021-08-17 15:13 |
| MOT test number | 745203715428     |
| Result          | <b>✓</b> Passed  |
|                 |                  |
| MOT #6          | 2021-03-02 13:58 |
| MOT test number | 643996593277     |
| Result          | <b>✓</b> Passed  |

CarCheck.co.uk page 3/11



MOT #5 2020-09-25 10:12

**MOT test number** 693406366704

MOT #4 2020-09-25 09:39

**MOT test number** 328129439735

Result × Failed

Fail Nearside Front Road wheel fixing missing (5.2.1 (a) (i))

MOT #3 2020-03-19 14:48

**MOT test number** 920940296775

Result \rightarrow Passed

MOT #2 2019-03-16 10:59

MOT test number 114525273316

Result 

✓ Passed

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

MOT #1 2018-03-29 14:46

**MOT test number** 250970408498

CarCheck.co.uk page 4/11



#### Tax & MOT check



X MOT

Tax expired: 11 April 2024

Expired: 16 August 2023

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 11 April 2024

18 days too late

16 August 2023

See MOT history

#### Tax calculation

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | В              |
| Single payment (12 months)              | £ 20,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 21,00,-      |

CarCheck.co.uk page 5/11



#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



HF15YKH

More info >

report date: 2024-03-28

# Owner history For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this CITROEN had different number plates. ober of plates furthe scinors

CarCheck.co.uk page 8/11



#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 11         |
| First mileage registration | 2015-03-30 |
| Last registration          | 2024-04-04 |
| Complete history           | See info   |



| Registration #1  | 2015-03-30 | 14 mi     |
|------------------|------------|-----------|
| Registration #2  | 2018-03-29 | 52.374 mi |
| Registration #3  | 2019-03-16 | 62.096 mi |
| Registration #4  | 2020-03-19 | 70.967 mi |
| Registration #5  | 2020-09-25 | 74.102 mi |
| Registration #6  | 2020-09-25 | 74.102 mi |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 0.074     |
| Registration #9  |            | 11.777 mi |
| Registration #10 |            | 0.074     |
| Registration #11 |            | 11.777 au |

More info >

CarCheck.co.uk page 10/11



# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 90%             |
| Children       | 85%             |
| Pedestrian     | 43%             |
| Safety systems | 97%             |
| Overall rating | 80%             |
| Video          | see crash video |



# Dimensions & weight

| Width               | 1826 mm |
|---------------------|---------|
| Height              | 1656 mm |
| Length              | 4597 mm |
| Wheel base          | 2840 mm |
| Kerb weight         | 1430 kg |
| Max. allowed weight | 2250 kg |

# Additional information

| Fuel tank capacity | 55 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 7                |
| Number of axles    | 2                |
| Engine number      | DYZJ4025065      |

CarCheck.co.uk page 11/11