



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Grey
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed Semi-Automatic

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.1 mpg
Consumption extra urban	44.1 mpg
Consumption combined	37.7 mpg
CO2 emission	179 g/km
CO2 label	I







Internet history

Entry 1

Date	2021-10-04
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-03
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	41
Total items failed	6

MOT #17 2023-12-04 15:52

MOT test number 300043002400

Result ✓ Passed

Next expiry date 2024-12-03

- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Front Registration plate deteriorated but not likely to be misread And rear (0.1 (b))
- Advice** Under-trays fitted obscuring some underside components

MOT #16 2022-10-10 09:09

MOT test number 901125540265

Result ✓ Passed

- Advice** Under-trays fitted obscuring some underside components
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #15 2021-10-04 15:50

MOT test number 884204046282

Result ✓ Passed

**MOT #14**

2021-10-04 11:15

MOT test number

725662294768

Result

✗ Failed

Fail Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #13**

2020-10-07 10:43

MOT test number

984578811601

Result

✓ Passed

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Battery insecure but not likely to fall from carrier (4.13 (a) (i))**MOT #12**

2019-09-30 11:30

MOT test number

889506040844

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2019-09-30 11:03

MOT test number

654230389442

Result**✗ Failed****Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #10**

2018-10-08 15:19

MOT test number

471456386172

Result**✓ Passed****Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Battery loose, Not insecure**MOT #9**

2018-10-08 09:29

MOT test number

259918560449

Result**✗ Failed****Advice** Child Seat fitted not allowing full inspection of adult belt**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Minor** Nearside Obligatory mirror slightly damaged (3.3 (b) (i))**Advice** Battery loose, Not insecure**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #8** 2017-04-15 09:08**MOT test number** 858086662597**Result** ✓ Passed**Advice** Offside rear tyre worn low inner edge**MOT #7** 2017-04-15 09:08**MOT test number** 207247182522**Result** ✗ Failed**Advice** Offside rear tyre worn low inner edge**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2016-05-14 16:04**MOT test number** 344512161308**Result** ✓ Passed**MOT #5** 2015-04-29 15:32**MOT test number** 719039515138**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Nail in nearside front tyre**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #4**

2014-04-03 11:52

MOT test number

978773994054

Result

✓ Passed

Advice Nearside Front Shock absorber has a light misting of oil (2.7.3)**Notice** OSR tyre wall perishing**Notice** NSR tyre wall perishing**Advice** Offside Front Shock absorber has slight corrosion to the casing (2.7.2a)**Notice** OSR tyre feathering on inner edge**Notice** NSR tyre feathering on inner edge**MOT #3**

2013-03-07 10:00

MOT test number

725666963042

Result

✓ Passed

MOT #2

2013-03-07 10:00

MOT test number

315706263096

Result

✗ Failed

Pass with rectification Nearside Stop lamp not working (1.2.1b)**MOT #1**

2012-03-09 09:53

MOT test number

538829762060

Result

✓ Passed

Notice Wiper blades slightly worn front**Advice** Nearside Outer Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Rear tyres slightly out of shape inner treads



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
3 December 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	3 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	EX08DZB
Plate since	2019-09-29
Current registration	EX08DZB
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-04-16
Last registration	2023-12-04
Complete history	See info



Registration #1	2008-04-16	21 mi
Registration #2	2012-03-09	36.792 mi
Registration #3	2013-03-07	47.455 mi
Registration #4	2014-04-03	58.383 mi
Registration #5	2015-04-29	67.581 mi
Registration #6	2016-05-14	77.102 mi
Registration #7	2017-04-15	82.539 mi
Registration #8	2017-04-15	82.539 mi
Registration #9	2018-10-08	93.718 mi
Registration #10	2019-05-29	101.277 mi
Registration #11	2019-05-29	101.277 mi
Registration #12	2019-05-29	101.277 mi
Registration #13	2019-05-29	101.277 mi
Registration #14	2019-05-29	101.277 mi
Registration #15	2019-05-29	101.277 mi
Registration #16	2019-05-29	101.277 mi
Registration #17	2019-05-29	101.277 mi
Registration #18	2019-05-29	101.277 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZV011339