





report date: 2024-03-29

### General information

Make	KIA
Model	OPTIMA CRDI 3 ISG
Colour	White
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	76.4 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/13



### Internet history

#### Entry 2

Date	2021-11-09
Pictures	0

Listing price <u>View report</u>

#### source: heycar.co.uk

#### Entry 1

Date	2021-11-08
Pictures	19
Listing price	View report









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-04
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	31
Total items failed	4

MOT #7		2023-10-05 11:37
MOT test	number	924549941290
Result		✓ Passed
Next expi	ry date	2024-11-04
Advice	Front exhaust bracket broken	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)
Advice	Epb lever broke but still functioning and able to operate hand brake	

MOT #6	2022-	10-26 12:55
MOT test i	number 902	2823093538
Result		✓ Passed
Advice	Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Front exhaust bracket broken	
Advice	Electronic parking brake defective but can be satisfactorily operated (1.1.6 (d))	

MOT #5	2021-11-05 16:37
MOT test number	884495798426
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

### MOT #4 2021-06-15 13:57

**MOT test number** 245104472104

Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Brake pad(s) wearing thin unable to view inner clearly (1.1.13 (a) (ii))	
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Brake pad(s) wearing thin unable to view inner clearly (1.1.13 (a) (ii))	
Advice	Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))	

CarCheck.co.uk page 4/13



Result

ΔΟ17RΔΧ

report date: 2024-03-29

**MOT #3** 2021-06-15 10:46

**MOT** test number 527196073844

× Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Central Front Registration plate does not conform to the specified requirements (0.1 (d)) Fail

**Advice** Offside Rear Brake pad(s) wearing thin unable to view inner clearly (1.1.13 (a) (ii))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

Fail Central Rear Registration plate does not conform to the specified requirements (0.1 (d))

**Advice** Nearside Rear Brake pad(s) wearing thin unable to view inner clearly (1.1.13 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #2** 2020-06-04 07:41

**MOT** test number 897736847809

Result ✓ Passed

Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1

MOT test number

123470455308

Result

Advice COVID-19 6 MONTH EXTENSION

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 November
Days left	186
MOT expiry date	4 November 2024
Full MOT history	See MOT history

### Tax calculation

-	
Vehicle class	49
Band	F
First licence fee (12 months)	£ 185,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

#### Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

*		
For how long did the current and previous owner(s) have this KIA? How many owners did Check it in the premium report and see all owner registrations. Download the full report is		
*********		
***************************************		
***************************************		
***************************************		
	More info	>
Plate changes		
See in this check if this KIA had different number plates.		
Number of plates		,
Current registration	NK NE	
Plate since		
Current registration	OK SIES	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-05-31
Last registration	2023-10-05
Complete history	See info



Registration #1	2017-05-31	19 mi
Registration #2	2020-06-04	43.090 mi
Registration #3	2021-06-15	53.427 mi
Registration #4	2021-06-15	53.427 mi
Registration #5	2021-11-05	55.840 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	86%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1860 mm
Height	1465 mm
Length	4855 mm
Wheel base	2805 mm
Kerb weight	1705 kg
Max. allowed weight	2070 kg

# Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 pa	ge 13/13

Number of axles 2

**Engine number** D4FDGH218117