





report date: 2024-03-28

General information

Make	FORD
Model	FIESTA STYLE PLUS TDCI
Colour	Silver
Year of manufacture	2010
Top speed	101 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	67.3 mpg
CO2 emission	110 g/km
CO2 label	В



CarCheck.co.uk page 1/13



MOT history

MOT expiry date	2025-01-06
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	37
Total items failed	2

MOT #12		2024-01-02 10:31
MOT test	number	907147730558
Result		✓ Passed
Next exp	iry date	2025-01-06
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deterior	prated (6.1.7 (g) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Rear Coil spring corroded both (5.3.1 (b) (i))	
Minor (4.8.1 (a)	Nearside Rear Lower Rear reflector defective or damaged by up to 50% of (i))	the reflecting surface
Advice	Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn both	h (5.1.2 (b) (i))

CarCheck.co.uk page 2/13



Advice

NJ60KPE report date: 2024-03-28

MOT #11 2023-01-07 15:01

MOT test number 178989004893

Advice Wheel caps fitted

Advice Offside Front Service brake binding but not excessively (1.2.1 (f))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

Advice Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn n/s and o/s (5.1.2 (b) (i))

Front Tyre worn close to legal limit/worn on edge n/s and o/s (5.2.3 (e))

Advice Play in steering rack inner joint(s)

MOT #10 2022-01-07 16:03

MOT test number 785362027271

Result Passed

Advice Steering column universal joint has slight wear or play (2.2.2 (c))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

CarCheck.co.uk page 3/13



Fail

NJ60KPE report date: 2024-03-28

MOT #9 2022-01-06 11:13 MOT test number 272186942005

Result × Failed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice Steering column universal joint has slight wear or play (2.2.2 (c))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8 2020-11-25 16:43

MOT test number 873261753389

Advice Steering column universal joint has slight wear or play (2.2.2 (c))

Advice Rear Exhaust heat shield loose

Advice Rear Direction indicator slightly discoloured Both sides (4.4.3 (a))

MOT #7 2019-05-23 11:47

MOT test number 256165965160

Advice Items removed from driver's view prior to test

Advice Offside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))

Advice Nearside Front Road wheel slightly distorted inner rim (5.2.2 (c) (i))

CarCheck.co.uk page 4/13



MOT test number

Result

Advice Both front brakes binding slightly - reqs attention

Advice Items removed from driver's view prior to test

Advice Both front wheel rims slightly buckled

MOT #5 2017-06-04 10:08 **MOT test number** 274415229804 Result ✓ Passed MOT #4 2016-04-30 14:49 **MOT** test number 515821217240 Result ✓ Passed **MOT** #3 2015-05-05 11:40 **MOT test number** 379315425119 Result ✓ Passed **Notice** Nearside rear tyre has uneven wear on inner tread

MOT #2		2014-04-23 11:03
MOT test	number	556863514102
Result		✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (3.5.1g)	
Notice	Nearside front tyre wearing on inner and outer edges	
Advice	Nearside Front Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 5/13



MOT #1 2013-05-08 08:57

MOT test number 527518323198

Result ✓ Passed

Advice

Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

Advice

Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	6 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-


CarCheck.co.uk page 7/13



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	UN CONTRACTOR
Current registration	OK OK
Plate since	******
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-09-01
Last registration	2024-01-02
Complete history	See info



Registration #1	2010-09-01	28 mi
Registration #2	2013-05-08	36.768 mi
Registration #3	2014-04-23	43.750 mi
Registration #4	2015-05-05	49.858 mi
Registration #5	2016-04-30	53.340 mi
Registration #6	2017-06-04	56.775 mi
Registration #7	2018-05-08	59.943 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		11.777 46
Registration #13		10.777 au

More info >

CarCheck.co.uk page 12/13



Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1973 mm
Height	1481 mm
Length	3950 mm
Kerb weight	1141 kg
Max. allowed weight	1535 kg

Additional information

Fuel tank capacity	40 I
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

9R21853