





report date: 2024-03-28

#### General information

Make	VOLVO
Model	S60 D3 SE LUX
Colour	Red
Year of manufacture	2013
Top speed	127 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	136 BHP
Max. torque	350 Nm at 2.250 rpm
Engine capacity	1.984 сс
Cylinders	5
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	72.4 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	С



CarCheck.co.uk page 1/12



## Internet history

#### Entry 1

Date	2021-06-25
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-04-15
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #11		2024-03-18 12:14
MOT test	number	624027220818
Result		✓ Passed
Next expi	y date	2025-04-15
Advice Offside Front Shock absorbers has light misting of oil (5.3.2 (b))		
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	

MOT #10		2023-03-20 11:56
MOT test	number	314657301312
Result		✓ Passed
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #9	2022-03-18 09:38
MOT test number	436087445113
Result	<b>✓</b> Passed
MOT #8	2021-04-16 10:55
MOT test number	688335687132
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



SF13VMJ

report date: 2024-03-28

MOT #7 2021-04-15 14:41

**MOT test number** 542840988514

Result X Failed

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #6 2019-12-17 16:19

**MOT test number** 415527083199

Result \( \sqrt{Passed} \)

**Advice** Items removed from driver's view prior to test

MOT #5 2018-09-24 12:25

**MOT test number** 300325522521

Result \rightarrow Passed

MOT #4 2018-02-21 16:48

**MOT test number** 724018097095

**Result** 
✓ Passed

**Advice** Front Tyre worn close to the legal limit both (4.1.E.1)

MOT #3 2017-02-27 15:38

**MOT test number** 230324688332

MOT #2 2017-02-27 13:06

**MOT test number** 353484084036

Result × Failed

**Fail** Offside Front Headlamp cleaning device obviously defective (1.7.2)

CarCheck.co.uk page 4/12



MOT #1 2016-02-22 12:10

**MOT test number** 888792792901

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	15 April 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



SF13VMJ

report date: 2024-03-28

#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		)
********		
***************************************		
	More info	>
Plate changes		
See in this check if this VOLVO had different number plates.		
Number of plates		7
Current registration	UK UK	
Plate since		
Current registration	UK NEZ	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-03-02
Last registration	2024-03-18
Complete history	See info



Registration #1	2013-03-02	14 mi
Registration #2	2016-02-22	20.992 mi
Registration #3	2017-02-27	29.287 mi
Registration #4	2017-02-27	29.287 mi
Registration #5	2018-02-21	37.183 mi
Registration #6	2018-09-24	41.385 mi
Registration #7	2019-12-17	51.936 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



## Dimensions & weight

Width	1865 mm
Height	1484 mm
Length	4628 mm
Wheel base	2776 mm
Kerb weight	1605 kg
Max. allowed weight	2090 kg

# Additional information

Fuel tank capacity	67 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 12