





report date: 2024-03-28

General information

| Make | PEUGEOT |
|---------------------|------------------------------|
| Model | PARTNER HDI PROFESSIONAL 625 |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 94 mph |
| 0 - 60 mph | 17.6 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 75 BHP |
|-------------------------|---------------------|
| Max. torque | 184 Nm at 1.500 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 61.4 mpg |
| Consumption combined | 56.5 mpg |
| CO2 emission | 131 g/km |
| CO2 label | E |



CarCheck.co.uk page 1/11



LF65KKW report date: 2024-03-28

MOT history

| MOT expiry date | 2024-07-23 |
|--------------------|------------|
| MOT pass rate | 71 % |
| MOT passed | 5 |
| Failed MOT tests | 2 |
| Total advice items | 17 |
| Total items failed | 3 |

| MOT #7 | | 2023-07-24 13:00 |
|----------------|---|------------------------|
| MOT test | number | 733033280335 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-07-23 |
| Advice | Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i)) | |
| Advice | Spare tyre defective | |
| Minor (b) (i)) | Nearside Registration plate lamp inoperative in the case of multiple lamps or | r light sources (4.7.1 |

| MOT #6 | | 2022-06-01 14:51 |
|----------------|--|------------------------|
| MOT test | number | 147388540754 |
| Result | | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Minor (b) (i)) | Nearside Registration plate lamp inoperative in the case of multiple lamps o | r light sources (4.7.1 |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge Also perished (5 | .2.3 (e)) |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge Also perished (5.2. | 3 (e)) |
| Advice | Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT #5 2022-06-01 14:51 **MOT** test number 192641413740 Result × Failed **Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge Also perished (5.2.3 (e)) **Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge Also perished (5.2.3 (e)) **Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #4 2021-04-22 14:18

MOT test number 963345683102

Result ✓ Passed

MOT #3 2021-04-22 09:40 MOT test number 247021253556

Result × Failed

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps Both (4.7.1 (b) (ii))

Fail Stop lamp(s) all not working (4.3.1 (a) (iii))

MOT #2 2019-11-11 10:22

MOT test number 321771780938

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1

MOT test number

180305016424

Result

Advice Front tyres wearing thin on outside

CarCheck.co.uk page 4/11



LF65KKW report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 May |
|------------------|-------------------|
| Days left | 366 |
| MOT expiry date | 23 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 39 |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months) | £ 151,25,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



LF65KKW report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



LF65KKW report date: 2024-03-28

Owner history

| e when miscory | |
|--|-------------|
| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations. | |
| ********* | |
| | |
| ************ | |
| | |
| | |
| | |
| | |
| | More info > |
| Plate changes See in this check if this PEUGEOT had different number plates. | |
| Number of plates | , |
| Current registration | UK UK |
| Plate since | |
| Current registration | AK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



LF65KKW report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



LF65KKW report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 8 |
| First mileage registration | 2015-11-27 |
| Last registration | 2023-07-24 |
| Complete history | See info |



| Registration #1 | 2015-11-27 | 14 mi |
|-----------------|------------|-----------|
| Registration #2 | 2018-11-08 | 39.004 mi |
| Registration #3 | 2019-11-11 | 50.090 mi |
| Registration #4 | 2021-04-22 | 63.175 mi |
| Registration #5 | | 11.777 es |
| Registration #6 | | 11.777 es |
| Registration #7 | | 11.777 es |
| Registration #8 | | 71.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Dimensions & weight

| Width | 2112 mm |
|---------------------|---------|
| Height | 1801 mm |
| Length | 4380 mm |
| Kerb weight | 1304 kg |
| Max. allowed weight | 1945 kg |

Additional information

| Fuel tank capacity | 60 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 3 |
| Engine number | JBEM0413270 |

CarCheck.co.uk page 11/11