



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 S
Colour	Grey
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	12.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	140 g/km
CO2 label	E





## MOT history

MOT expiry date	2022-02-10
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	51
Total items failed	17

MOT #13 2021-02-11 14:25

MOT test number 807958809749

Result ✓ Passed

Next expiry date 2022-02-10

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust emits blue smoke during acceleration and at idle (8.2.1.2 (g))
- Advice** Front Items removed from driver's view prior to test screen
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge and has a nail in it (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Advice** Rear Exhaust silencer slightly loose rear exhaust mount missing (8.1.1 (b) (i))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #12**

2021-02-03 12:42

**MOT test number**

887998622229

**Result****✗ Failed**

- Fail** Offside Side repeater light intensity significantly reduced (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))
- Advice** Exhaust emits blue smoke during acceleration and at idle (8.2.1.2 (g))
- Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge and has a nail in it (5.2.3 (e))
- Advice** Front Items removed from driver's view prior to test screen
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))
- Fail** Offside Rear Direction indicator not working (4.4.1 (a) (ii))
- Advice** Rear Exhaust silencer slightly loose rear exhaust mount missing (8.1.1 (b) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**MOT #11**

2019-12-27 11:50

**MOT test number**

221386148618

**Result**

✓ Passed

- Advice** Rear exhaust bracket missing
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear axle corroded

**MOT #10**

2019-12-27 10:33

**MOT test number**

525320384064

**Result**

✗ Failed

- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Advice** Rear exhaust bracket missing
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Rear axle corroded
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #9**

2018-12-27 14:48

**MOT test number**

829833313945

**Result**

✓ Passed

- Advice** Offside Rear tyre has screw in tread
- Advice** Front Brake pad(s) wearing thin advise full inspection with wheels removed (1.1.13 (a) (ii))
- Minor** Central Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front exhaust mounting fractured
- Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

**MOT #8**

2018-12-27 12:02

**MOT test number**

918818179675

**Result**

✗ Failed

- Advice** Offside Rear tyre has screw in tread
- Minor** Central Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Front exhaust mounting fractured
- Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake pad(s) wearing thin advise full inspection with wheels removed (1.1.13 (a) (ii))
- Fail** Offside Obligatory mirror insecure damaged and insecure (3.3 (b) (ii))
- Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions wrong direction of rotation (5.2.3 (i))

**MOT #7** 2017-06-30 10:12**MOT test number** 738330165314**Result** ✓ Passed

- Advice** Windscreen chipped
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear exhaust bracket corroded
- Advice** Offside Rear coil spring corroded (2.4.C.1b)

**MOT #6** 2016-06-08 09:24**MOT test number** 415559187175**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-06-08 11:09**MOT test number** 797629555144**Result** ✓ Passed**MOT #4** 2015-06-08 09:35**MOT test number** 449199255187**Result** ✗ Failed

- Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Fail** Offside Rear coil spring broken (2.4.C.1a)

**MOT #3** 2014-04-23 09:19**MOT test number** 907393514113**Result** ✓ Passed



MOT #2	2013-04-25 09:52
MOT test number	766495913125
Result	✓ Passed
Notice	Rear tyres perished
Advice	Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2012-04-23 14:23
MOT test number	427694612137
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
30 April 2021

X

MOT

Expired:  
10 February 2022

Tax status	Expired at 30 April 2021
Days left	1094 days too late
MOT expiry date	10 February 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2009-04-30
Last registration	2021-02-11
Complete history	<a href="#">See info</a>



Registration #1	2009-04-30	27 mi
Registration #2	2012-04-23	20.605 mi
Registration #3	2013-04-25	23.391 mi
Registration #4	2014-04-23	28.500 mi
Registration #5	2015-06-08	33.130 mi
Registration #6	2015-06-08	33.133 mi
Registration #7	2016-06-08	40.818 mi
Registration #8	2016-06-08	40.818 mi
Registration #9	2016-06-08	40.818 mi
Registration #10	2016-06-08	40.818 mi
Registration #11	2016-06-08	40.818 mi
Registration #12	2016-06-08	40.818 mi
Registration #13	2016-06-08	40.818 mi
Registration #14	2016-06-08	40.818 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1748 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1245 kg
Max. allowed weight	1640 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

